

# All System Diagnostic Report

The Report is created by **THINKCAR**

## Repair Shop

Shop Name:bosch service centre

Address:564 Steve Biko Road

Telephone:0123355737

Email:karika@boschgezina.co.za

Sn:988579800333

Time:2024-08-06 13:05:52

Technician Name:Riaan

Customer Name:citton cars

Order no:

Service fee:

Notes:

## Vehicle Information

Year:2018

Make:HYUNDAI

Model:Grand i10/Xcent(BA)

VIN:MALA851CLJM738168

Displacement:G 1.2 MPI

Odometer:94092 km

Vehicle Software Version:V10.28

## Inspection Result

The following systems are OK:

- 1.ECM (Engine Control Module)
- 2.ABS (Anti-lock Braking System)
- 3.Airbag(Event #1)
- 4.Airbag(Event #2)
- 5.Cluster Module
- 6.EPS (Electronic Power Steering)
- 7.IMM (Immobilizer)