

# All System Diagnostic Report

The Report is created by **THINKCAR**

---

## Repair Shop

Shop Name: bosch service centre  
Address: 564 Steve Biko Road  
Telephone: 0123355737  
Sn: 988579800333  
Time: 11/12/2024 08:21:30  
Technician Name: Riaan  
Customer Name: citton

---

## Vehicle Information

Year: 2017  
Make: EUROFORD  
Model: Fiesta MY2013  
VIN: WF0DXXGAKDHU38573  
Odometer: 97237 km  
Vehicle Software Version: V10.76

---

## Inspection Result

The following systems are OK:

1. ABS (Anti-Lock Braking System)
2. ACM (Audio Control Module)
3. APIM (Accessory Protocol Interface Module)
4. BCMII (Body Control Module)
5. DDM (Driver Front Door Module)
6. FCDIM (Front Control/Display Interface Module)
7. GPSM (Global Positioning System Module)
8. IPC (Instrument Panel Control Module)
9. PCM (Powertrain Control Module)
10. PDM (Passenger Front Door Module)
11. PSCM (Power Steering Control Module)
12. RCM (Restraint Control Module)