Make	MERCEDES-BENZ
Model	GLE 350d 4MATIC
Vin	WDC1660242A739111
Engine Specifications	Diesel
Engine Specifications Vehicle Type	Diesel

Year	2016
Km	157612
Transmission	Automatic
Colour	SILVER
Branch	Bosch Car Service
Warranty Plan	N/A

Interior					
Radio / Entertainment	Within Specification	<b>~</b>	Aircon Controls	Within Specification	•
Cluster	Good Condition	•	Electric Windows	Within Specification	•

Exterior					
Windscreen	Within Specification		Mag Wheels	Within Specification	-
Side Mirrors / Electric	Within Specification	lacksquare	Wiper Blades	Within Specification	•

BOSCH VEHICLE INSPECTION					
Engine					
Oil Service	SERVICE DONE Km		Dip Stick	Within Specification	•
Oil Filter	Renewed		Oil Filler Cap	Within Specification	•
Fuel/Diesel Filter	No Visible Leaks		Fan Belt	Within Specification	<b>~</b>
Air Filter	Within Specification		Fan belt Tensioner	Within Specification	•
Cabin Filter	Within Specification		Alternator Belt	Within Specification	<b>~</b>
Spark Plugs	Not Applicable		Power Steering Belt	Not Applicable	•
Brake Fluid	No Visible Leaks		Aircon Belt	Within Specification	•
Antifreeze	No Visible Leaks		Multi V belt	Within Specification	<b>~</b>
Rear Main Seal	No Visible Leaks		Engine Mountings	Within Specification	<b>~</b>
Sump/Gasket	No Visible Leaks		PCV Valve	Within Specification	•

Braking System		
Front Brake Pads	-Select-	•
Front Brake Discs	Within Specification	•
Front Brake Sensor	Within Specification	•
Rear Brake Pads	-Select-	•
Rear Brake Discs	Within Specification	•
Rear Brake Sensor	Renewed	lacksquare
Rear Drums	Not Applicable	•
Rear Linings	-Select-	•
Brake Master	No Visible Leaks	•
Hand Brake	Within Specification	
Brake Calipers	No Visible Leaks	•
Brake Hose	No Visible Leaks	•

Cooling System		
Radiator	No Visible Leaks	lacksquare
Radiator Hoses	No Visible Leaks	lacksquare
Waterpump	Within Specification	•
Thermostat	Within Specification	-
Aircon Gas	No Visible Leaks	•
Aircon Pump	Within Specification	•
Aircon Condensor	No Visible Leaks	lacksquare
Interior Fan	Within Specification	lacksquare
Interior Radiator	No Visible Leaks	•

Fueling System		
Intake Manifold	Within Specification	-
Throttle	Within Specification	•
Turbo	Within Specification	•
Injectors	Within Specification	•
Fuel Pump	Within Specification	•
Fuel Lines	No Visible Leaks	•

Ignition System		
Ignition Coils	Not Applicable	•
Glow Plugs	No Fault Code	lacksquare
Distrubutor	Not Applicable	•
HT Leads	Not Applicable	•



## **BOSCH INSPECTION REPORT**

Steering & Suspension		
Steering Rack	Within Specification	•
Power Steering Pump	Not Applicable	<b>•</b>
Wheel Alignment	Within Specification	lacksquare
CV Joints	Within Specification	<b>•</b>
CV Boots	No Visible Leaks	•
Shocks Front	No Visible Leaks	•
Shock Mountings Front	Within Specification	•
Shocks Rear	No Visible Leaks	•
Stabilizer Links	Within Specification	•
Wheel Bearings	Within Specification	•
Bearing Hubs	Within Specification	•
Control Arms	Within Specification	<b>—</b>
Sideshafts/Seal	No Visible Leaks	•
Propshaft	Within Specification	<b>—</b>
Wheel Nuts/Studs	Within Specification	•
Tyres & Spare	Within Specification	•
Mag Wheels/Hub Caps	Within Specification	•

Transmission & Clutch		
Clutch Kit	Not Applicable	<b>—</b>
Clutch Master	Not Applicable	<b>—</b>
Clutch Slave	Not Applicable	<b>\</b>
Clutch Cable	Not Applicable	<b>T</b>
Gearbox	Within Specification	<b>T</b>
Gear & Diff oil	No Visible Leaks	<b>—</b>
Auto Transmission	Within Specification	<b>—</b>
Gear Selector	Good Condition	<b>—</b>
Gear Linkages	Within Specification	<b>T</b>

Ignition System		
Diagnostics	No Fault Code	•
Cyl Leakage Test	Not Applicable	-
Road Test	Within Specification	-
Handling	Within Specification	•

Concluding hemarks	
Bosch Technician	General Comments
Raymond Mncube	
NEW Technician	Date of Inspection
	24-Jan-2025



**PRETORIA** 

