

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name:bosch service centre
Address:564 Steve Biko Road
Telephone:0123355737
Sn:988579800333
Time:11/13/2024 07:12:32
Technician Name:Mike botha

Vehicle Information

Year:2015
Make:AUDI
VIN:WAUZZZ8U6FR039296
Displacement:G 1.0 T-GDI KAPPA
Odometer:94480 miles
Vehicle Software Version:V10.30

Inspection Result

The following systems are OK:

- 1.01 Engine Electronics
- 2.02 Transmission Electronics
- 3.03 Brake Electronics
- 4.08 Climate Control Module
- 5.09 Electronic Central Electric
- 6.10 Parallel Parking 2
- 7.15 Airbag
- 8.16 Steering Column Electronics Systems
- 9.17 Instrument Cluster
- 10.19 Data Bus OBD Interface
- 11.25 Anti-Theft Immobilizer
- 12.42 Driver's Door Electronics
- 13.44 Power Steering
- 14.52 Passenger's Door Electronics
- 15.55 Headlamp Range Control
- 16.5F Information Electronics 1
- 17.62 Left Rear Door Electronics
- 18.72 Right Rear Door Electronics