

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name:bosch service centre

Address:564 Steve Biko Road

Telephone:0123355737

Email:lukas@boschgezina.co.za

Sn:988579800333

Time:2024-07-05 13:07:39

Technician Name:Lesego

Order no:

Service fee:

Notes:

Vehicle Information

Year:2016.01

Make:BMW

Model:X1 sDrive20d

VIN:WBAHU120005A39538

Odometer:113470 km

Vehicle Software Version:V10.30

Inspection Result

CAS (Car Access System - CAS/FEM/BDC) 1 problems exist

**1.0301A0 Power Window Regulator, Rear Passenger Door: Permanent
System Not Normalised.**

The following systems are OK:

- 1.SRS (Supplemental Inflatable Restraint System - AIRBAG/SGM-SIM)
- 2.ZGM (Central Gateway Module)
- 3.ECM (Engine Control Module - DME/DDE)
- 4.TCM (Transmission Control Module - EGS)
- 5.ABS (Anti-Lock Braking System - DSC)
- 6.PMA (Parking Assistant)
- 7.EPS (Electronic Power Steering)
- 8.FZD (Function Center, Roof)
- 9.IC (Instrument Cluster - INSTR)
- 10.ECALL (Emergency Call)
- 11.CIC (Car Information Computer)
- 12.ZBE/CON (Controller)
- 13.AC (Air Conditioning - IHKA)