

# All System Diagnostic Report

The Report is created by **THINKCAR**

## Repair Shop

Shop Name:bosch service centre  
Address:564 Steve Biko Road  
Telephone:0123355737  
Email:karika@boschgezina.co.za  
Sn:988579800333  
Time:11/11/2024 09:57:37  
Technician Name:Dries

## Vehicle Information

Make:SUZUKI  
VIN:TSMJYB22S00140378  
Displacement:G 1.4 DOHC  
Odometer:96649 km  
Vehicle Software Version:V10.36

## Inspection Result

The following systems are OK:

- 1.ECM ( Engine Control Module )
- 2.TCM ( Transmission Control Module )
- 3.ABS ( Anti-Lock Braking System )
- 4.EPS ( Electronic Power Steering )
- 5.SRS ( Supplemental Inflatable Restraint System/Airbag )
- 6.AC ( Air Conditioning )
- 7.BCM ( Body Control Module )
- 8.4WD ( 4 Wheel Drive )
- 9.KLS ( Keyless Start )
- 10.IPC ( Combination Meter / Meter/ M&A )
- 11.ALC ( Headlight Auto Leveling )