

# All System Diagnostic Report

The Report is created by **THINKCAR**

## Repair Shop

Shop Name:bosch service centre

Address:564 Steve Biko Road

Telephone:0123355737

Email:karika@boschgezina.co.za

Sn:988579800333

Time:10/30/2024 12:42:45

Technician Name:shaun

## Vehicle Information

Year:2015.01

Make:BMW

Model:420d

VIN:WBA3P12080K407285

Displacement:G 1.4 DOHC

Odometer:100181 km

Vehicle Software Version:V10.46

## Inspection Result

The following systems are OK:

- 1.SRS (Supplemental Inflatable Restraint System - AIRBAG/SGM-SIM)
- 2.ZGM (Central Gateway Module)
- 3.ECM (Engine Control Module - DME/DDE)
- 4.EKPS (Electronic Fuel Pump)/RLM\_1L (Tail Light Module, Outer Left)
- 5.TCM (Transmission Control Module - EGS)
- 6.ICM (Integrated Chassis Management)/RLM\_2L (Tail Light Module, Inner Left)
- 7.ABS (Anti-Lock Braking System - DSC)
- 8.EPS (Electronic Power Steering)
- 9.CAS (Car Access System - CAS/FEM/BDC)
- 10.FZD (Function Center, Roof)
- 11.GWS (Gear Selector Switch)
- 12.IC (Instrument Cluster - INSTR)
- 13.ECALL (Emergency Call)
- 14.CIC (Car Information Computer)
- 15.ZBE/CON (Controller)
- 16.FRM (Footwell Module)/TSGFA (Driver Door Control Unit)
- 17.AC (Air Conditioning - IHKA)