

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name:
Address:
Telephone:N/A
Sn:988579800333
Time:12/20/2024 15:59:20
Technician Name:hennie

Vehicle Information

Year:2019
Make:MAZDA
Model:MAZDA2 / DEMIO
VIN:MM6DJ2HA6KW441144
Displacement:G 1.4 DOHC
Odometer:53678 km
Vehicle Software Version:V10.38

Inspection Result

The following systems are OK:
1.BCM#1 (Body Control Module)
2.IC (Instrument Cluster)
3.PCM (Powertrain Control Module)
4.RCM (Restraint Control Module)
5.ABS (Anti-Lock Brake System)
6.EPS (Electronic Power Steering)
7.ESU (Electric Supply Unit)
8.SSU#1 (Start Stop Unit)