

# All System Diagnostic Report

The Report is created by **THINKCAR**

## Repair Shop

Shop Name:citton cars  
Address:564 Steve Biko Road  
Telephone:0123355737  
Email:jaco@boschgezina.co.za  
Sn:988579800333  
Time:2024-03-27 09:36:37  
Technician Name:Ricardo  
Order no:  
Service fee:  
Notes:

## Vehicle Information

Year:2019  
Make:MAZDA  
Model:CX-3  
VIN:JM6DK2W7AK0413829  
Displacement:G 1.0 MPI KAPPA  
Odometer:55235 km  
Vehicle Software Version:V10.34

## Inspection Result

The following systems are OK:

- 1.BCM#1 (Body Control Module)
- 2.IC (Instrument Cluster)
- 3.PCM (Powertrain Control Module)
- 4.RCM (Restraint Control Module)
- 5.TCM (Transmission Control Module)
- 6.ABS (Anti-Lock Brake System)
- 7.EPB (Electrical Parking Brake)
- 8.EPS (Electronic Power Steering)
- 9.ESU (Electric Supply Unit)
- 10.SSU#1 (Start Stop Unit)