Make	SUZUKI		
Model	CELERIO 1.0 GA		
Vin	MA3KFC42S0054141	2	
Engine Specifications	1.0	Petrol	
Vehicle Type	H/B		

Year	2018
Km	128250
Transmission	Manual
Colour	WHITE
Branch	Bosch Car Service
Warranty Plan	N/A

Interior					
Radio / Entertainment	Within Specification	-	Aircon Controls	Within Specification	-
Cluster	Within Specification	•	Electric Windows	Within Specification	•

Exterior					
Windscreen	Within Specification		Mag Wheels	Within Specification	-
Side Mirrors / Electric	Within Specification	lacksquare	Wiper Blades	Within Specification	•

BOSCH VEHICLE INSPECTION					
Engine					
Oil Service		Km	Dip Stick	Within Specification	•
Oil Filter	Renewed	•	Oil Filler Cap	Within Specification	•
Fuel/Diesel Filter	Within Specification	•	Fan Belt	No Cracks	•
Air Filter	Within Specification	•	Fan belt Tensioner	Within Specification	-
Cabin Filter	Within Specification	•	Alternator Belt	No Cracks	•
Spark Plugs	Renewed	•	Power Steering Belt	No Cracks	•
Brake Fluid	Within Specification	•	Aircon Belt	No Cracks	-
Antifreeze	Within Specification	•	Multi V belt	No Cracks	•
Rear Main Seal	No Visible Leaks	•	Engine Mountings	Within Specification	—
Sump/Gasket	No Visible Leaks	•	PCV Valve	Within Specification	•

Braking System		
Front Brake Pads	100%	•
Front Brake Discs	Within Specification	
Front Brake Sensor	Not Applicable	•
Rear Brake Pads	80%	•
Rear Brake Discs	Within Specification	•
Rear Brake Sensor	Not Applicable	•
Rear Drums	Within Specification	•
Rear Linings	80%	•
Brake Master	Within Specification	•
Hand Brake	Within Specification	
Brake Calipers	Within Specification	•
Brake Hose	Within Specification	•

Cooling System		
Radiator	Within Specification	
Radiator Hoses	Within Specification	•
Waterpump	Within Specification	•
Thermostat	Within Specification	
Aircon Gas	Within Specification	•
Aircon Pump	Within Specification	-
Aircon Condensor	Within Specification	•
Interior Fan	Within Specification	•
Interior Radiator	No Visible Leaks	•

Fueling System		
Intake Manifold	Within Specification	•
Throttle	Within Specification	•
Turbo	Not Applicable	\rightarrow
Injectors	Within Specification	~
Fuel Pump	Within Specification	~
Fuel Lines	Within Specification	•

Ignition System		
Ignition Coils	Within Specification	•
Glow Plugs	Not Applicable	•
Distrubutor	Not Applicable	~
HT Leads	Not Applicable	•



BOSCH INSPECTION REPORT

Steering & Suspension		
Steering Rack	Within Specification	•
Power Steering Pump	Within Specification	•
Wheel Alignment	Within Specification	•
CV Joints	Within Specification	•
CV Boots	Within Specification	•
Shocks Front	Within Specification	•
Shock Mountings Front	Within Specification	•
Shocks Rear	Within Specification	•
Stabilizer Links	Within Specification	•
Wheel Bearings	Within Specification	•
Bearing Hubs	Within Specification	•
Control Arms	Within Specification	•
Sideshafts/Seal	No Visible Leaks	•
Propshaft	Not Applicable	•
Wheel Nuts/Studs	Within Specification	•
Tyres & Spare	Within Specification	•
Mag Wheels/Hub Caps	Within Specification	•

Transmission & Clutch		
Clutch Kit	Renewed	•
Clutch Master	Not Applicable	•
Clutch Slave	Not Applicable	•
Clutch Cable	Within Specification	T
Gearbox	Within Specification	•
Gear & Diff oil	Within Specification	•
Auto Transmission	Not Applicable	•
Gear Selector	Within Specification	—
Gear Linkages	Within Specification	•

Ignition System		
Diagnostics	Within Specification	\
Cyl Leakage Test	No Visible Leaks	•
Road Test	Within Specification	-
Handling	Within Specification	~

Concluding Remarks	
Bosch Technician	General Comments
Elias Makubela	
Lilas ivianubeia	
NEW Technician	Date of Inspection



