Make	MAZDA	
Model	MAZDA2 1.5 DYNAMIC A/T 5Dr	
Vin	MM6DJ2HAAJW341600	
Engine Specifications	1.5 Pe	trol
Vehicle Type	H/B	
Service Plan	N/A	

Year	2018
Km	115844
Transmission	Automatic
Colour	RED
Branch	Bosch Car Service
Warranty Plan	N/A

Interior					
Radio / Entertainment	Good Condition	-	Aircon Controls	Good Condition	•
Cluster	Good Condition	•	Electric Windows	Good Condition	•

Exterior					
Windscreen	Good Condition	<b>—</b>	Mag Wheels	Good Condition	-
Side Mirrors / Electric	Good Condition	lacksquare	Wiper Blades	Good Condition	•

BOSCH VEHICLE INSPECTION					
Engine					
Oil Service		Km	Dip Stick	Good Condition	•
Oil Filter	Good Condition	•	Oil Filler Cap	Good Condition	•
Fuel/Diesel Filter	Good Condition	•	Fan Belt	Good Condition	•
Air Filter	Good Condition	•	Fan belt Tensioner	Good Condition	•
Cabin Filter	Good Condition	-	Alternator Belt	Good Condition	•
Spark Plugs	Good Condition	•	Power Steering Belt	Good Condition	•
Brake Fluid	Good Condition	-	Aircon Belt	Good Condition	•
Antifreeze	Good Condition	<b>~</b>	Multi V belt	Good Condition	•
Rear Main Seal	Good Condition	<b>-</b>	Engine Mountings	Good Condition	•
Sump/Gasket	Good Condition	•	PCV Valve	Good Condition	•

Braking System		
Front Brake Pads	80%	•
Front Brake Discs	Good Condition	lacksquare
Front Brake Sensor	Not Applicable	
Rear Brake Pads	-Select-	•
Rear Brake Discs	Not Applicable	•
Rear Brake Sensor	Not Applicable	•
Rear Drums	Good Condition	•
Rear Linings	60%	lacksquare
Brake Master	Good Condition	lacksquare
Hand Brake	Good Condition	lacksquare
Brake Calipers	Good Condition	•
Brake Hose	Good Condition	lacksquare

Cooling System		
Radiator	Good Condition	•
Radiator Hoses	Good Condition	•
Waterpump	Good Condition	•
Thermostat	Good Condition	•
Aircon Gas	Good Condition	•
Aircon Pump	Good Condition	•
Aircon Condensor	Good Condition	•
Interior Fan	Good Condition	<b>—</b>
Interior Radiator	Good Condition	•

Fueling System		
Intake Manifold	Good Condition	-
Throttle	Good Condition	•
Turbo	Not Applicable	•
Injectors	Good Condition	•
Fuel Pump	Good Condition	•
Fuel Lines	Good Condition	•

Ignition System		
Ignition Coils	Good Condition	•
Glow Plugs	Not Applicable	•
Distrubutor	Not Applicable	<b>\</b>
HT Leads	Not Applicable	•



## **BOSCH INSPECTION REPORT**

Steering & Suspension		
Steering Rack	Good Condition	<b>—</b>
Power Steering Pump	Good Condition	<b>~</b>
Wheel Alignment	Good Condition	lacksquare
CV Joints	Good Condition	<b>•</b>
CV Boots	Good Condition	lacksquare
Shocks Front	Good Condition	<b>—</b>
Shock Mountings Front	Good Condition	lacksquare
Shocks Rear	Good Condition	lacksquare
Stabilizer Links	Good Condition	<b>•</b>
Wheel Bearings	Good Condition	•
Bearing Hubs	Within Specification	•
Control Arms	Good Condition	<b>—</b>
Sideshafts/Seal	Good Condition	•
Propshaft	Not Applicable	<b>—</b>
Wheel Nuts/Studs	Good Condition	<b>—</b>
Tyres & Spare	Good Condition	<b>—</b>
Mag Wheels/Hub Caps	Good Condition	<b>T</b>

Transmission & Clutch		
Clutch Kit	Not Applicable	<b>—</b>
Clutch Master	Not Applicable	<b>—</b>
Clutch Slave	Not Applicable	<b>T</b>
Clutch Cable	Not Applicable	<b>V</b>
Gearbox	Not Applicable	<b>V</b>
Gear & Diff oil	Not Applicable	<b>V</b>
Auto Transmission	Good Condition	<b>—</b>
Gear Selector	Good Condition	<b>—</b>
Gear Linkages	Good Condition	<b>T</b>

Ignition System		
Diagnostics	Not Applicable	-
Cyl Leakage Test	Not Applicable	-
Road Test	Not Applicable	-
Handling	Not Applicable	-

Concluding Nemarks	
Bosch Technician	General Comments
-Select-	
NEW Technician	Date of Inspection



