

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name:bosch service centre

Address:564 Steve Biko Road

Telephone:0123355737

Email:jaco@boschgezina.co.za

Sn:988579800333

Time:11/01/2024 12:43:35

Technician Name:Christiaan

Vehicle Information

Year:2018

Make:MAZDA

Model:MAZDA2 / DEMIO

VIN:MM6DJ2HAAJW341600

Displacement:D 1.4 TCI-U2

Odometer:115861 km

Vehicle Software Version:V10.36

Inspection Result

The following systems are OK:

- 1.BCM#1 (Body Control Module)
- 2.IC (Instrument Cluster)
- 3.PCM (Powertrain Control Module)
- 4.RCM (Restraint Control Module)
- 5.TCM (Transmission Control Module)
- 6.ABS (Anti-Lock Brake System)
- 7.CMU (Connectivity Master Unit)
- 8.EPS (Electronic Power Steering)
- 9.ESU (Electric Supply Unit)
- 10.SSU#1 (Start Stop Unit)