Make	FORD		
Model	ECOSPORT 1.0 ECOBOOST TREND A/T		
Vin	WF01XXERK1JR41660		
Engine Specifications	1.0 Petrol ▼		
Vehicle Type	SUV		
Service Plan	N/A		

Year	2019
Km	78651
Transmission	Automatic
Colour	WHITE
Branch	Bosch Car Service
Warranty Plan	N/A

Interior					
Radio / Entertainment	No Fault Code	—	Aircon Controls	No Fault Code	•
Cluster	No Fault Code	V	Electric Windows	No Fault Code	•

Exterior					
Windscreen	Within Specification	-	Mag Wheels	Within Specification	•
Side Mirrors / Electric	No Fault Code	lacksquare	Wiper Blades	Good Condition	\rightarrow

BOSCH VEHICLE INSPECTION					
Engine					
Oil Service		77896 Km	Dip Stick	Within Specification	V
Oil Filter	No Visible Leaks	lacksquare	Oil Filler Cap	Within Specification	•
Fuel/Diesel Filter	Not Applicable	lacksquare	Fan Belt	Not Applicable	V
Air Filter	Within Specification	lacksquare	Fan belt Tensioner	Within Specification	•
Cabin Filter	Within Specification	—	Alternator Belt	No Cracks	•
Spark Plugs	No Fault Code		Power Steering Belt	Not Applicable	-
Brake Fluid	No Visible Leaks	_	Aircon Belt	No Cracks	-
Antifreeze	No Visible Leaks	_	Multi V belt	No Cracks	_
Rear Main Seal	No Visible Leaks	_	Engine Mountings	Within Specification	-
Sump/Gasket	No Visible Leaks	lacksquare	PCV Valve	No Visible Leaks	•

Braking System		
Front Brake Pads	80%	•
Front Brake Discs	Within Specification	•
Front Brake Sensor	Not Applicable	•
Rear Brake Pads	-Select-	•
Rear Brake Discs	Not Applicable	•
Rear Brake Sensor	Not Applicable	•
Rear Drums	Within Specification	•
Rear Linings	60%	•
Brake Master	No Visible Leaks	•
Hand Brake	Within Specification	
Brake Calipers	No Visible Leaks	•
Brake Hose	No Visible Leaks	•

Cooling System		
Radiator	No Visible Leaks	•
Radiator Hoses	No Visible Leaks	•
Waterpump	No Visible Leaks	•
Thermostat	No Visible Leaks	•
Aircon Gas	No Visible Leaks	•
Aircon Pump	No Fault Code	•
Aircon Condensor	No Visible Leaks	•
Interior Fan	No Fault Code	•
Interior Radiator	No Visible Leaks	T

Fueling System		
Intake Manifold	Within Specification	•
Throttle	No Fault Code	•
Turbo	No Fault Code	•
Injectors	No Fault Code	•
Fuel Pump	No Fault Code	V
Fuel Lines	No Visible Leaks	•

Ignition System		
Ignition Coils	No Fault Code	_
Glow Plugs	Not Applicable	•
Distrubutor	Not Applicable	-
HT Leads	Not Applicable	lacksquare



BOSCH INSPECTION REPORT

Steering & Suspension		
Steering Rack	Within Specification	•
Power Steering Pump	Not Applicable	•
Wheel Alignment	Within Specification	•
CV Joints	Within Specification	•
CV Boots	No Visible Leaks	•
Shocks Front	No Visible Leaks	•
Shock Mountings Front	Within Specification	•
Shocks Rear	No Visible Leaks	•
Stabilizer Links	Within Specification	•
Wheel Bearings	Within Specification	•
Bearing Hubs	Within Specification	•
Control Arms	Within Specification	•
Sideshafts/Seal	No Visible Leaks	•
Propshaft	Not Applicable	•
Wheel Nuts/Studs	Within Specification	•
Tyres & Spare	Within Specification	•
Mag Wheels/Hub Caps	Within Specification	~

Transmission & Clutch		
Clutch Kit	Not Applicable	
Clutch Master	Not Applicable	
Clutch Slave	Not Applicable	
Clutch Cable	Not Applicable	•
Gearbox	No Visible Leaks	
Gear & Diff oil	No Visible Leaks	
Auto Transmission	No Visible Leaks	
Gear Selector	Within Specification	
Gear Linkages	Within Specification	•

Ignition System		
Diagnostics	No Fault Code	-
Cyl Leakage Test	No Visible Leaks	-
Road Test	Within Specification	-
Handling	Within Specification	-

Concluding Remarks	
Bosch Technician	General Comments
Dries Olwagen	
NEW Technician	Date of Inspection



PRETORIA

