Make	ABARTH		
Model	ABARTH 595 1.4T TURISMO		
Vin	ZFA3120000J41820	3	
Engine Specifications	1.4	Petrol	•
Vehicle Type	H/B		

Year	2016
Km	91330
Transmission	Manual
Colour	WHITE
Branch	Bosch Car Service
Warranty Plan	N/A

Interior					
Radio / Entertainment	No Fault Code	•	Aircon Controls	No Fault Code	•
Cluster	No Fault Code	•	Electric Windows	No Fault Code	•

Exterior					
Windscreen	Within Specification	—	Mag Wheels	Within Specification	•
Side Mirrors / Electric	No Fault Code	lacksquare	Wiper Blades	Renewed	•

BOSCH VEHICLE INSPECTION					
Engine					
Oil Service		91092 Km	Dip Stick	Within Specification	•
Oil Filter	No Visible Leaks	-	Oil Filler Cap	Within Specification	•
Fuel/Diesel Filter	Not Applicable	—	Fan Belt	No Cracks	•
Air Filter	Within Specification	-	Fan belt Tensioner	Within Specification	•
Cabin Filter	Within Specification	-	Alternator Belt	No Cracks	•
Spark Plugs	No Fault Code	-	Power Steering Belt	Not Applicable	•
Brake Fluid	No Visible Leaks	-	Aircon Belt	No Cracks	•
Antifreeze	No Visible Leaks	-	Multi V belt	No Cracks	•
Rear Main Seal	No Visible Leaks	-	Engine Mountings	Within Specification	•
Sump/Gasket	No Visible Leaks	•	PCV Valve	Within Specification	•

Braking System		
Front Brake Pads	60%	•
Front Brake Discs	Within Specification	
Front Brake Sensor	No Fault Code	•
Rear Brake Pads	60%	•
Rear Brake Discs	Within Specification	•
Rear Brake Sensor	No Fault Code	•
Rear Drums	Not Applicable	•
Rear Linings	-Select-	•
Brake Master	No Visible Leaks	•
Hand Brake	Within Specification	•
Brake Calipers	No Visible Leaks	•
Brake Hose	No Visible Leaks	•

Cooling System		
Radiator	No Visible Leaks	•
Radiator Hoses	No Visible Leaks	•
Waterpump	No Visible Leaks	•
Thermostat	No Visible Leaks	-
Aircon Gas	No Visible Leaks	•
Aircon Pump	No Fault Code	•
Aircon Condensor	No Visible Leaks	•
Interior Fan	No Fault Code	\rightarrow
Interior Radiator	No Visible Leaks	•

Fueling System		
Intake Manifold	No Visible Leaks	•
Throttle	No Fault Code	•
Turbo	No Fault Code	•
Injectors	No Fault Code	•
Fuel Pump	No Fault Code	~
Fuel Lines	No Visible Leaks	•

Ignition System		
Ignition Coils	No Fault Code	•
Glow Plugs	Not Applicable	•
Distrubutor	Not Applicable	~
HT Leads	Not Applicable	•



BOSCH INSPECTION REPORT

Steering & Suspension		
Steering Rack	No Visible Leaks	—
Power Steering Pump	Not Applicable	•
Wheel Alignment	Within Specification	•
CV Joints	Within Specification	•
CV Boots	No Visible Leaks	•
Shocks Front	No Visible Leaks	•
Shock Mountings Front	Within Specification	•
Shocks Rear	Good Condition	•
Stabilizer Links	Within Specification	•
Wheel Bearings	Within Specification	•
Bearing Hubs	Within Specification	lacksquare
Control Arms	Within Specification	•
Sideshafts/Seal	No Visible Leaks	•
Propshaft	Not Applicable	•
Wheel Nuts/Studs	Within Specification	•
Tyres & Spare	Within Specification	•
Mag Wheels/Hub Caps	Within Specification	—

Transmission & Clutch		
Clutch Kit	Within Specification	lacksquare
Clutch Master	No Visible Leaks	-
Clutch Slave	No Visible Leaks	V
Clutch Cable	Not Applicable	V
Gearbox	No Visible Leaks	▼
Gear & Diff oil	No Visible Leaks	V
Auto Transmission	Not Applicable	•
Gear Selector	Within Specification	V
Gear Linkages	Within Specification	V

Ignition System		
Diagnostics	No Fault Code	-
Cyl Leakage Test	No Visible Leaks	-
Road Test	Within Specification	-
Handling	Within Specification	-

Concluding Remarks		
Bosch Technician		General Comments
Dries Olwagen	•	
NEW Technician		Date of Inspection



