Make	SUZUKI		
Model	JIMNY 1.3 A/T		
Vin	JSAFJB43V00642783		
Engine Specifications	1.3	Petrol	-
Vehicle Type	SUV		
Service Plan	N/A		

Year	2015
Km	100805
Transmission	Automatic
Colour	WHITE
Branch	Bosch Car Service
Warranty Plan	N/A

Interior					
Radio / Entertainment	Good Condition	-	Aircon Controls	Good Condition	•
Cluster	Good Condition	•	Electric Windows	Good Condition	•

Exterior					
Windscreen	Good Condition	•	Mag Wheels	Good Condition	•
Side Mirrors / Electric	Good Condition	—	Wiper Blades	Good Condition	•

BOSCH VEHICLE INSPECTION					
Engine					
Oil Service		Km	Dip Stick	Good Condition	•
Oil Filter	Good Condition	lacksquare	Oil Filler Cap	Good Condition	•
Fuel/Diesel Filter	Good Condition	lacksquare	Fan Belt	Good Condition	•
Air Filter	Good Condition	lacksquare	Fan belt Tensioner	Good Condition	•
Cabin Filter	Good Condition	—	Alternator Belt	Good Condition	•
Spark Plugs	Good Condition		Power Steering Belt	Good Condition	•
Brake Fluid	Good Condition	-	Aircon Belt	Good Condition	•
Antifreeze	Good Condition	—	Multi V belt	Good Condition	•
Rear Main Seal	Good Condition	—	Engine Mountings	Good Condition	•
Sump/Gasket	Good Condition	V	PCV Valve	Good Condition	•

Braking System		
Front Brake Pads	80%	•
Front Brake Discs	Good Condition	lacksquare
Front Brake Sensor	Not Applicable	•
Rear Brake Pads	-Select-	lacksquare
Rear Brake Discs	Not Applicable	•
Rear Brake Sensor	Not Applicable	•
Rear Drums	Good Condition	•
Rear Linings	60%	•
Brake Master	Good Condition	
Hand Brake	Good Condition	•
Brake Calipers	Good Condition	•
Brake Hose	Good Condition	•

Cooling System		
Radiator	Good Condition	
Radiator Hoses	Good Condition	•
Waterpump	Good Condition	-
Thermostat	Good Condition	•
Aircon Gas	Good Condition	•
Aircon Pump	Good Condition	•
Aircon Condensor	Good Condition	•
Interior Fan	Good Condition	•
Interior Radiator	Good Condition	•

Fueling System		
Intake Manifold	Good Condition	•
Throttle	Good Condition	•
Turbo	Not Applicable	•
Injectors	Good Condition	•
Fuel Pump	Good Condition	•
Fuel Lines	Good Condition	•

Ignition System		
Ignition Coils	Good Condition	•
Glow Plugs	Not Applicable	•
Distrubutor	Not Applicable	~
HT Leads	Not Applicable	•



BOSCH INSPECTION REPORT

Steering & Suspension		
Steering Rack	Good Condition	-
Power Steering Pump	Good Condition	•
Wheel Alignment	Good Condition	-
CV Joints	Good Condition	•
CV Boots	Good Condition	•
Shocks Front	Good Condition	•
Shock Mountings Front	Good Condition	•
Shocks Rear	Good Condition	•
Stabilizer Links	Good Condition	•
Wheel Bearings	Good Condition	•
Bearing Hubs	Good Condition	•
Control Arms	Good Condition	•
Sideshafts/Seal	Good Condition	•
Propshaft	Not Applicable	•
Wheel Nuts/Studs	Good Condition	•
Tyres & Spare	Good Condition	•
Mag Wheels/Hub Caps	Good Condition	•

Transmission & Clutch		
Clutch Kit	Not Applicable	-
Clutch Master	Not Applicable	~
Clutch Slave	Not Applicable	~
Clutch Cable	Not Applicable	~
Gearbox	Not Applicable	~
Gear & Diff oil	Not Applicable	~
Auto Transmission	Good Condition	~
Gear Selector	Good Condition	~
Gear Linkages	Good Condition	V

Ignition System		
Diagnostics	Good Condition	
Cyl Leakage Test	Good Condition	~
Road Test	Good Condition	_
Handling	Good Condition	~

Concluding Nemarks	
Bosch Technician	General Comments
-Select-	
NEW Technician	Date of Inspection



