Make	RENAULT	
Model	DUSTER 1.5 dCI DYNAMIQUE	
Vin	VF1HSRADF5643873	2
Engine Specifications	1.5	Diesel
Vehicle Type	SUV	
Service Plan	N/A	

Year	2017
Km	83412
Transmission	Manual
Colour	BLACK
Branch	Bosch Car Service
Warranty Plan	N/A

Interior					
Radio / Entertainment	Not Applicable	•	Aircon Controls	Good Condition	•
Cluster	Good Condition	-	Electric Windows	Good Condition	V

Exterior					
Windscreen	Good Condition	—	Mag Wheels	Good Condition	•
Side Mirrors / Electric	Good Condition	lacksquare	Wiper Blades	Not Applicable	•

BOSCH VEHICLE INSPECTION					
Engine					
Oil Service	SERVICE DUE Km		Dip Stick	Within Specification	•
Oil Filter	Not Applicable		Oil Filler Cap	No Visible Leaks	•
Fuel/Diesel Filter	Within Specification		Fan Belt	No Cracks	•
Air Filter	Within Specification		Fan belt Tensioner	Within Specification	•
Cabin Filter	Within Specification		Alternator Belt	No Cracks	•
Spark Plugs	Not Applicable		Power Steering Belt	Not Applicable	•
Brake Fluid	Good Condition		Aircon Belt	No Cracks	-
Antifreeze	Good Condition		Multi V belt	No Cracks	T
Rear Main Seal	No Visible Leaks ▼		Engine Mountings	Good Condition	•
Sump/Gasket	No Visible Leaks ▼		PCV Valve	Within Specification	•

Braking System		
Front Brake Pads	20%	—
Front Brake Discs	Within Specification	•
Front Brake Sensor	Not Applicable	•
Rear Brake Pads	-Select-	•
Rear Brake Discs	Not Applicable	—
Rear Brake Sensor	Not Applicable	•
Rear Drums	Within Specification	•
Rear Linings	60%	•
Brake Master	Good Condition	•
Hand Brake	Within Specification	—
Brake Calipers	Good Condition	—
Brake Hose	No Visible Leaks	—

Cooling System		
Radiator	Within Specification	•
Radiator Hoses	No Visible Leaks	•
Waterpump	Within Specification	•
Thermostat	Within Specification	•
Aircon Gas	Good Condition	•
Aircon Pump	Within Specification	•
Aircon Condensor	Good Condition	•
Interior Fan	Good Condition	•
Interior Radiator	No Visible Leaks	•

Fueling System		
Intake Manifold	Within Specification	-
Throttle	Within Specification	•
Turbo	Within Specification	•
Injectors	Within Specification	•
Fuel Pump	Within Specification	•
Fuel Lines	No Visible Leaks	•

Ignition System		
Ignition Coils	Not Applicable	•
Glow Plugs	Within Specification	lacksquare
Distrubutor	Not Applicable	•
HT Leads	Not Applicable	•



BOSCH INSPECTION REPORT

Steering & Suspension		
Steering Rack	Within Specification	—
Power Steering Pump	Not Applicable	—
Wheel Alignment	Within Specification	—
CV Joints	Good Condition	—
CV Boots	No Visible Leaks	•
Shocks Front	Good Condition	•
Shock Mountings Front	Good Condition	—
Shocks Rear	Good Condition	•
Stabilizer Links	Good Condition	•
Wheel Bearings	Good Condition	•
Bearing Hubs	Within Specification	•
Control Arms	Good Condition	•
Sideshafts/Seal	No Visible Leaks	•
Propshaft	Not Applicable	•
Wheel Nuts/Studs	Good Condition	lacksquare
Tyres & Spare	Good Condition	•
Mag Wheels/Hub Caps	Good Condition	•

Transmission & Clutch		
Clutch Kit	Within Specification	•
Clutch Master	Within Specification	~
Clutch Slave	Within Specification	•
Clutch Cable	Not Applicable	~
Gearbox	Within Specification	~
Gear & Diff oil	Within Specification	~
Auto Transmission	Not Applicable	—
Gear Selector	Within Specification	~
Gear Linkages	Within Specification	~

Ignition System		
Diagnostics	No Visible Leaks	_
Cyl Leakage Test	No Visible Leaks	_
Road Test	Good Condition	_
Handling	Good Condition	~

Concluding Remarks		

Bosch Technician	General Comments
-Select-	

NEW Technician

Date of Inspection

20-Aug-2024



