Make	HYUNDAI		
Model	GRAND i10 1.0 MOTION A/T		
Vin	MALA851AMKN	M943923	
Engine Specifications	1.0	Petrol	<b>V</b>
Vehicle Type	D/C		
Service Plan	N/A		

Year	2019
Km	118212
Transmission	Automatic
Colour	RED
Branch	Bosch Car Service
Warranty Plan	N/A

Interior					
Radio / Entertainment	Good Condition	-	Aircon Controls	Good Condition	•
Cluster	Good Condition	•	Electric Windows	Good Condition	•

Exterior					
Windscreen	Good Condition	<b>—</b>	Mag Wheels	Good Condition	•
Side Mirrors / Electric	Good Condition	<b>~</b>	Wiper Blades	Within Specification	•

BOSCH VEHICLE INSPECTION					
Engine					
Oil Service		Km	Dip Stick	Good Condition	•
Oil Filter	Good Condition	<b>—</b>	Oil Filler Cap	Good Condition	•
Fuel/Diesel Filter	Within Specification	<b>—</b>	Fan Belt	Good Condition	•
Air Filter	Within Specification	<b>—</b>	Fan belt Tensioner	Not Applicable	•
Cabin Filter	Within Specification	<b>—</b>	Alternator Belt	Not Applicable	•
Spark Plugs	Within Specification	<b>—</b>	Power Steering Belt	Not Applicable	<b>—</b>
Brake Fluid	Within Specification	_	Aircon Belt	Not Applicable	•
Antifreeze	Good Condition		Multi V belt	Good Condition	<b>T</b>
Rear Main Seal	Good Condition	•	Engine Mountings	Good Condition	<b>—</b>
Sump/Gasket	Good Condition	•	PCV Valve	Good Condition	•

Braking System		
Front Brake Pads	80%	•
Front Brake Discs	Good Condition	•
Front Brake Sensor	Good Condition	•
Rear Brake Pads	-Select-	•
Rear Brake Discs	Not Applicable	•
Rear Brake Sensor	Not Applicable	•
Rear Drums	Good Condition	•
Rear Linings	60%	
Brake Master	Good Condition	•
Hand Brake	Good Condition	•
Brake Calipers	Good Condition	
Brake Hose	Good Condition	•

Cooling System		
Radiator	Good Condition	•
Radiator Hoses	Good Condition	•
Waterpump	Good Condition	•
Thermostat	Good Condition	•
Aircon Gas	Good Condition	•
Aircon Pump	Good Condition	•
Aircon Condensor	Good Condition	•
Interior Fan	Good Condition	•
Interior Radiator	Good Condition	<b>T</b>

Fueling System		
Intake Manifold	Good Condition	-
Throttle	Good Condition	•
Turbo	Not Applicable	•
Injectors	Good Condition	•
Fuel Pump	Good Condition	•
Fuel Lines	Good Condition	•

Ignition System		
Ignition Coils	Not Applicable	•
Glow Plugs	Not Applicable	lacksquare
Distrubutor	Not Applicable	•
HT Leads	Not Applicable	<b>—</b>



## **BOSCH INSPECTION REPORT**

Steering & Suspension		
Steering Rack	Within Specification	•
Power Steering Pump	Within Specification	•
Wheel Alignment	Within Specification	lacksquare
CV Joints	Good Condition	•
CV Boots	Good Condition	•
Shocks Front	Within Specification	•
Shock Mountings Front	Within Specification	•
Shocks Rear	Within Specification	<b>~</b>
Stabilizer Links	Within Specification	<b>~</b>
Wheel Bearings	Good Condition	<b>~</b>
Bearing Hubs	Good Condition	<b>—</b>
Control Arms	Good Condition	<b>—</b>
Sideshafts/Seal	Good Condition	<b>~</b>
Propshaft	Not Applicable	•
Wheel Nuts/Studs	Good Condition	<b>~</b>
Tyres & Spare	Good Condition	•
Mag Wheels/Hub Caps	Good Condition	<b>—</b>

Transmission & Clutch		
Clutch Kit	Within Specification	•
Clutch Master	Not Applicable	•
Clutch Slave	Not Applicable	•
Clutch Cable	Not Applicable	•
Gearbox	Good Condition	•
Gear & Diff oil	Not Applicable	•
Auto Transmission	Good Condition	•
Gear Selector	Good Condition	•
Gear Linkages	Good Condition	<b>T</b>

Ignition System		
Diagnostics	Not Applicable	-
Cyl Leakage Test	Not Applicable	-
Road Test	Not Applicable	-
Handling	Not Applicable	-

Concluding Remarks	
Bosch Technician	General Comments
-Select-	
NEW Technician	Date of Inspection



