

Engine

# **BOSCH INSPECTION REPORT**

JOB CARD NUMBER 15565

Make	MERCEDES-BENZ
Model	A 220d STYLE A/T
Vin	WBAYN32070EM83439
Engine Specifications	Petrol
Vehicle Type	H/B
Service Plan	N/A

Year	2016
Km	96758
Transmission	Automatic
Colour	WHITE
Branch	Bosch Car Service
Warranty Plan	N/A

Interior					
Radio / Entertainment	Within Specification	•	Aircon Controls	Not Applicable	•
Cluster	Within Specification	•	Electric Windows	Good Condition	•

Exterior					
Windscreen	Good Condition	-	Mag Wheels	Good Condition	-
Side Mirrors / Electric	Good Condition	•	Wiper Blades	Not Applicable	•

## **BOSCH VEHICLE INSPECTION**

Oil Service	SERVICE DUE Km	Dip Stick	Within Specification	-
Oil Filter	Not Applicable	Oil Filler Cap	No Visible Leaks	•
Fuel/Diesel Filter	Within Specification	Fan Belt	Within Specification	•
Air Filter	Within Specification	Fan belt Tensioner	Within Specification	•
Cabin Filter	Within Specification	Alternator Belt	Within Specification	•
Spark Plugs	Within Specification	Power Steering Belt	Not Applicable	-
Brake Fluid	Good Condition	Aircon Belt	Within Specification	-
Antifreeze	Good Condition	Multi V belt	Within Specification	•
Rear Main Seal	No Visible Leaks	Engine Mountings	Good Condition	-
Sump/Gasket	No Visible Leaks	PCV Valve	Within Specification	•

# BOSCH INSPECTION REPORT

	<b>~</b> ·
Braking	System

Front Brake Pads	-Select-	-
Front Brake Discs	Within Specification	-
Front Brake Sensor	Not Applicable	-
Rear Brake Pads	-Select-	-
Rear Brake Discs	Within Specification	-
Rear Brake Sensor	Within Specification	-
Rear Drums	Not Applicable	-
Rear Linings	-Select-	-
Brake Master	Good Condition	•
Hand Brake	Within Specification	•
Brake Calipers	Good Condition	-
Brake Hose	No Visible Leaks	•

Cooling System		
Radiator	Within Specification	•
Radiator Hoses	No Visible Leaks	•
Waterpump	Within Specification	•
Thermostat	Within Specification	-
Aircon Gas	Not Applicable	-
Aircon Pump	Within Specification	•
Aircon Condensor	Good Condition	-
Interior Fan	Good Condition	-
Interior Radiator	No Visible Leaks	-

Fueling System		
Intake Manifold	Within Specification	•
Throttle	Within Specification	•
Turbo	Within Specification	•
Injectors	Within Specification	•
Fuel Pump	Within Specification	•
Fuel Lines	No Visible Leaks	•

Ignition System		
Ignition Coils	Not Applicable	•
Glow Plugs	Within Specification	•
Distrubutor	Not Applicable	-
HT Leads	Not Applicable	•



# **BOSCH INSPECTION REPORT**

JOB CARD NUMBER 15565

Steering & Suspension		
Steering Rack	Within Specification	•
Power Steering Pump	Not Applicable	•
Wheel Alignment	Within Specification	-
CV Joints	Good Condition	-
CV Boots	No Visible Leaks	•
Shocks Front	Good Condition	-
Shock Mountings Front	Good Condition	•
Shocks Rear	Good Condition	•
Stabilizer Links	Good Condition	-
Wheel Bearings	Good Condition	-
Bearing Hubs	Within Specification	•
Control Arms	Good Condition	•
Sideshafts/Seal	No Visible Leaks	•
Propshaft	Not Applicable	-
Wheel Nuts/Studs	Good Condition	•
Tyres & Spare	Good Condition	-
Mag Wheels/Hub Caps	Good Condition	•

Transmission & Clutch		
Clutch Kit	Not Applicable	•
Clutch Master	Not Applicable	•
Clutch Slave	Not Applicable	•
Clutch Cable	Not Applicable	•
Gearbox	Not Applicable	•
Gear & Diff oil	Within Specification	•
Auto Transmission	Within Specification	•
Gear Selector	Within Specification	•
Gear Linkages	Within Specification	•

Ignition System		
Diagnostics	Not Applicable	•
Cyl Leakage Test	No Visible Leaks	•
Road Test	Good Condition	•
Handling	Good Condition	•

#### **Concluding Remarks**

## Bosch Technician

**NEW Technician** 

**RIAAN MEINTJIES** 

-Select-

## General Comments

Date of Inspection

02-Sep-2024



## BOSCH CAR SERVICE PRETORIA

a: 564 Steve Biko Road, Gezina, Pretoria 0084 t: 012 335 5737 e: reception@boschgezina.co.za

