

Engine

BOSCH INSPECTION REPORT

JOB CARD NUMBER 16138

Make	KIA	
Model	RIO 1.2 LS 5DR	
Vin	KNADB518LN674426	6
Engine Specifications	1.2	Petrol
Vehicle Type	H/B	
Service Plan	N/A	

Year	2023
Km	49008
Transmission	Manual
Colour	BLUE
Branch	Bosch Car Service
Warranty Plan	N/A

Interior					
Radio / Entertainment	Within Specification	•	Aircon Controls	Good Condition	•
Cluster	Within Specification	•	Electric Windows	Good Condition	•

Exterior					
Windscreen	Good Condition	•	Mag Wheels	Good Condition	•
Side Mirrors / Electric	Good Condition	•	Wiper Blades	Good Condition	-

BOSCH VEHICLE INSPECTION

Oil ServiceKmDip StickWithin SpecificationImage: Constraint of the specificationOil FilterWithin SpecificationImage: Constraint of the specificationOil Filter CapNo Visible LeaksImage: Constraint of the specificationAir FilterWithin SpecificationImage: Constraint of the specificationFan BeltWithin SpecificationImage: Constraint of the specificationCabin FilterWithin SpecificationImage: Constraint of the specificationFan belt TensionerWithin SpecificationImage: Constraint of the specificationSpark PlugsWithin SpecificationImage: Constraint of the specificationPower Steering BeltNot ApplicableImage: Constraint of the specificationBrake FluidGood ConditionImage: Constraint of the specificationImage: Constraint of the specificationImage: Constraint of the specificationImage: Constraint of the specificationRear Main SealNo Visible LeaksImage: Constraint of the specificationImage: Constraint of the specificationImage: Constraint of the specificationImage: Constraint of the specificationSump/GasketNo Visible LeaksImage: Constraint of the specificationImage: Constraint of the specificationImage: Constraint of the specificationImage: Constraint of the specificationSump/GasketNo Visible LeaksImage: Constraint of the specificationImage: Constraint of the specificationImage: Constraint of the specificationSump/GasketNo Visible LeaksImage: Constraint of the specificationImage: Constraint of the specificationImage: Constraint of the sp						
Fuel/Diesel Filter Within Specification Fan Belt Within Specification Fan belt Tensioner Within Specification Alternator Belt Within Specification Alternator Belt Within Specification Power Steering Belt Not Applicable Aircon Belt Within Specification Multi V belt Within Specification Engine Mountings Within Specification 	Oil Service		Km	Dip Stick	Within Specification	•
Air FilterWithin SpecificationImage: Control of the sectionFan belt TensionerWithin SpecificationImage: Control of the sectionCabin FilterWithin SpecificationImage: Control of the sectionAlternator BeltWithin SpecificationImage: Control of the sectionSpark PlugsWithin SpecificationImage: Control of the sectionPower Steering BeltNot ApplicableImage: Control of the sectionBrake FluidGood ConditionImage: Control of the sectionImage: Control of the sectionMulti V beltWithin SpecificationImage: Control of the sectionAntifreezeNo Visible LeaksImage: Control of the sectionImage: Control of the sectionImage: Control of the sectionImage: Control of the sectionRear Main SealNo Visible LeaksImage: Control of the sectionImage: Control of the sectionImage: Control of the section	Oil Filter	Within Specification	-	Oil Filler Cap	No Visible Leaks	•
Cabin Filter Within Specification Image: All and the specification Image: All and the specification Spark Plugs Within Specification Image: All and the specification <	Fuel/Diesel Filter	Within Specification	-	Fan Belt	Within Specification	•
Spark Plugs Within Specification Image: Power Steering Belt Not Applicable Brake Fluid Good Condition Image: Power Steering Belt Not Applicable Antifreeze Good Condition Image: Power Steering Belt Within Specification Rear Main Seal No Visible Leaks Image: Power Steering Belt Within Specification	Air Filter	Within Specification	-	Fan belt Tensioner	Within Specification	•
Brake Fluid Good Condition Image: Condition Aircon Belt Within Specification Antifreeze Good Condition Image: Condition Multi V belt Within Specification Rear Main Seal No Visible Leaks Image: Condition Image: Condition Image: Condition	Cabin Filter	Within Specification	-	Alternator Belt	Within Specification	-
Antifreeze Good Condition Image: Multi V belt Within Specification Rear Main Seal No Visible Leaks Image: Multi V belt Within Specification	Spark Plugs	Within Specification	-	Power Steering Belt	Not Applicable	•
Rear Main Seal No Visible Leaks Image: Constraint of the co	Brake Fluid	Good Condition	-	Aircon Belt	Within Specification	•
	Antifreeze	Good Condition	-	Multi V belt	Within Specification	•
Sump/Gasket No Visible Leaks PCV Valve Within Specification	Rear Main Seal	No Visible Leaks	-	Engine Mountings	Within Specification	•
	Sump/Gasket	No Visible Leaks	-	PCV Valve	Within Specification	•

BOSCH INSPECTION REPORT

Braking System		
Front Brake Pads	-Select-	•
Front Brake Discs	Within Specification	•
Front Brake Sensor	Not Applicable	-
Rear Brake Pads	-Select-	-
Rear Brake Discs	Not Applicable	-
Rear Brake Sensor	Not Applicable	-
Rear Drums	Within Specification	-
Rear Linings	-Select-	-
Brake Master	Good Condition	-
Hand Brake	Within Specification	•
Brake Calipers	Good Condition	-
Brake Hose	No Visible Leaks	•

Cooling System		
Radiator	Within Specification	•
Radiator Hoses	No Visible Leaks	-
Waterpump	Within Specification	•
Thermostat	Within Specification	•
Aircon Gas	Good Condition	•
Aircon Pump	Within Specification	-
Aircon Condensor	Good Condition	~
Interior Fan	Good Condition	~
Interior Radiator	No Visible Leaks	~

Fueling System		
Intake Manifold	Within Specification	•
Throttle	Within Specification	•
Turbo	Not Applicable	•
Injectors	Within Specification	•
Fuel Pump	Within Specification	•
Fuel Lines	No Visible Leaks	•

Ignition System		
Ignition Coils	Within Specification	-
Glow Plugs	Not Applicable	•
Distrubutor	Not Applicable	-
HT Leads	Not Applicable	-



BOSCH INSPECTION REPORT

Steering & Suspension		
Steering Rack	Within Specification	•
Power Steering Pump	Not Applicable	•
Wheel Alignment	Within Specification	•
CV Joints	Good Condition	•
CV Boots	No Visible Leaks	•
Shocks Front	No Visible Leaks	•
Shock Mountings Front	Good Condition	•
Shocks Rear	Good Condition	•
Stabilizer Links	Good Condition	•
Wheel Bearings	Good Condition	•
Bearing Hubs	Within Specification	•
Control Arms	Good Condition	•
Sideshafts/Seal	No Visible Leaks	•
Propshaft	Not Applicable	•
Wheel Nuts/Studs	Good Condition	•
Tyres & Spare	Good Condition	•
Mag Wheels/Hub Caps	Good Condition	-

Transmission & Clutch		
Clutch Kit	Within Specification	•
Clutch Master	Within Specification	•
Clutch Slave	Within Specification	•
Clutch Cable	Not Applicable	•
Gearbox	Within Specification	•
Gear & Diff oil	Within Specification	•
Auto Transmission	Not Applicable	•
Gear Selector	Within Specification	•
Gear Linkages	Within Specification	•

Ignition System		
Diagnostics	No Fault Code	-
Cyl Leakage Test	No Visible Leaks	-
Road Test	Good Condition	•
Handling	Good Condition	•

Concluding Remarks

Bosch Technician

NEW Technician

RIAAN MEINTJIES

-Select-

General Comments

Date of Inspection

27-Sep-2024



BOSCH CAR SERVICE PRETORIA

a: 564 Steve Biko Road, Gezina, Pretoria 0084 t: 012 335 5737 e: reception@boschgezina.co.za

