

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name:

Address:

Telephone:N/A

Email:juan-dre@boschgezina.co.za

Sn:988579800333

Time:11/18/2024 16:17:38

Technician Name:Raymond

Vehicle Information

Make:MITSUBISHI

VIN:MMBJLKK10NH044640

Displacement:G 2.0 MPI

Odometer:69931 km

Vehicle Software Version:V10.36

Inspection Result

The following systems are OK:

- 1.MPI/GDI/DIESEL
- 2.AT/CVT/A-MT/TC-SST
- 3.ABS/ASC/ASTC/WSS
- 4.SRS-Air Bag
- 5.Air Conditioner
- 6.ETACS
- 7.KOS/Immo/Keyless
- 8.Meter
- 9.Steering Angle Sensor
- 10.LIN
- 11.Gateway