

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name:bosch service centre

Address:564 Steve Biko Road

Telephone:0123355737

Email:pieter@boschgezina.co.za

Sn:988579800333

Time:2024-08-13 07:41:26

Technician Name:Raymond

Order no:

Service fee:

Notes:

Vehicle Information

Make:SUZUKI

VIN:MBHHWBA3S00450709

Displacement:G 2.0 NU MPI

Odometer:023367 km

Vehicle Software Version:V10.26

Inspection Result

The following systems are OK:

- 1.ECM (Engine Control Module)
- 2.ABS (Anti-Lock Braking System)
- 3.EPS (Electronic Power Steering)
- 4.SRS (Supplemental Inflatable Restraint System/Airbag)
- 5.BCM (Body Control Module)