

Bosch Service Inspection Certificate



BATTERY DETAILS

Inspection No:

± Age 2021
 Make Hyundai No. veave

Registration No: 5Z 29 X 09A

Job Card No: 57192 km

SERVICE	OK	Not Ok	Rectified	BREAKING SYSTEM	OK	Not Ok	Rectified	STEERING SYSTEM	OK	Not Ok	Rectified		
1 Service	✓			50 Brake Fluid C#	✓			100 Ball Joints	✓				
2 Spark Plugs	✓			51 Disc Pads Front mm	✓			101 Tie Rod Ends	✓				
3 Points & Condenser	✓			52 Pad Sensors Front	✓			102 Control Arm	✓				
4 Oil	✓			53 Discs Front mm	✓			103 Drag Link	✓				
5 Oil Filter	✓			54 Brake Caliper	✓			104 Stabiliser Arm	✓				
6 Fuel Filter	✓			55 Brake Caliper Leak(s)	✓			DRIVE LINE			OK	Not Ok	Rectified
7 Air Filter	✓			56 Disc Pads Rear mm	✓			105 Side Shaft Oil Leak(s)	✓				
8 Pollen Filter	✓			57 Pad Sensors Rear	✓			106 Front Wheel Bearings	✓				
9 Other Filter(s)	✓			58 Drums Rear mm	✓			107 Front Bearing Hubs	✓				
10 Wiper Blades	✓			59 Disc Rear mm	✓			108 Rear Wheel Bearings	✓				
11 Windscreen Washers	✓			60 Rear Linings mm	✓			109 Rear Wheel Bearing Hubs	✓				
12 Pedal Rubbers	✓			61 Rear Cylinders	✓			110 CV Shafts	✓				
ADDITIVES MISC				62 Rear Cylinder Leak(s)	✓			111 CV Boots	✓				
13 Brake Cleaner	✓			63 Handbrake Lining mm	✓			112 Shocks	✓				
14 Radiator Flush	✓			64 Handbrake Cable	✓			113 Springs	✓				
15 Carb Cleaner	✓			65 Brake Master Cylinder	✓			114 Shock Mountings	✓				
16 Engine Flush	✓			66 Master Cylinder Leak(s)	✓			115 Wheel Nuts/Studs	✓				
TRANSMISSION				67 ABS System	✓			116 Tyres & Spare Pressure	✓				
17 Transmission	✓			68 Brake Hoses	✓			117 Tyres & Spare Condition	✓				
18 Transmission Oil	✓			CLUTCH SYSTEM			OK	Not Ok	Rectified				
19 Transmission Oil Leak(s)	✓			69 Clutch Fluid C#	✓			118 Grease Points	✓				
20 Transfer Box	✓			70 Clutch Operation	✓			119 Prop Shaft(s)	✓				
21 Transfer Box Oil	✓			71 Clutch Master	✓			EXHAUST SYSTEM			OK	Not Ok	Rectified
22 Transfer Box air Leak(s)	✓			72 Clutch Master Leak	✓			120 Exhaust Silencer	✓				
23 Differential	✓			73 Clutch Slave	✓			121 Catalytic Converter	✓				
24 Differential Oil	✓			74 Clutch Slave Leak C#	✓			122 Flange Gasket	✓				
25 Differential Oil Leak(s)	✓			75 Clutch Cable	✓			123 Exhaust Manifold Gasket	✓				
26 Differential Lock	✓			COOLING SYSTEM			OK	Not Ok	Rectified				
27 Differential Mounting(s)	✓			76 Water Leaks	✓			124 Turbo Gasket(s)	✓				
28 Transmission Mounting	✓			77 Reservoir Bottle	✓			125 Hangers	✓				
ENGEN				78 Antifreeze — C#	✓			ELECTRICAL			OK	Not Ok	Rectified
29 Engine Oil Leak(s)	✓			79 Cooling Fan	✓			126 ECU	✓				
30 Oil Filler Cap	✓			80 Radiator Hoses	✓			127 Headlights - Dim	✓				
31 Cam Belt	✓			81 Water Pump	✓			128 Headlights - Bright	✓				
32 Cam Belt Tensioner	✓			82 Thermostat	✓			129 Fog Lights	✓				
33 Drive Belt(s)/V-Belt(s)	✓			83 Radiator	✓			130 Brake Lights	✓				
34 Tensioner/Pulleys	✓			84 Cooling System Pressure Test	✓			131 Park Lights	✓				
35 Hydraulic Lifters	✓			85 Hose Clamps	✓			132 Dash Lights	✓				
36 Tappet Noise	✓			86 Radiator Cap	✓			133 Interior Lights	✓				
37 Throttle Assembly	✓			87 Cap Pressure Test	✓			134 Flicker Lights Left	✓				
38 Turbo	✓			IGNITION SYSTEM			OK	Not Ok	Rectified				
39 Carburetor	✓			88 Coil(s)	✓			135 Flicker Lights Right	✓				
40 Injectors	✓			89 Distributor	✓			136 Spot Lights	✓				
41 Fuel Pump	✓			90 Distributor Cap	✓			137 Reverse Light(s)	✓				
42 Fuel Line	✓			91 Rotor	✓			138 Starter	✓				
43 Vacuum System	✓			92 High Tension Leads	✓			139 Alternator	✓				
44 Relative Compression Test	✓			STEERING SYSTEM			OK	Not Ok	Rectified				
45 Engine Mounting	✓			93 Steering System	✓			140 Battery	✓				
AIR CONDITIONER				94 Steering System Leak(s)	✓			141 Battery Terminals	✓				
46 Climate Control	✓			95 Power Steering Pump	✓			142 Battery Water	✓				
47 Climate Temp C#	✓			96 Power Steering Fluid	✓			143 Power Windows	✓				
48 Compressor	✓			97 Power Steering Pipes	✓			144 Side Mirrors	✓				
49 Service Air-Con System	✓			98 Steering Boots	✓			145 Instrument	✓				
				99 Steering Rack	✓			146 Sensors	✓				
								147 Seat Belts	✓				
								148 Seats	✓				
								149 Diagnostic Check	✓				
								150 Hooter	✓				

NB: INTERNAL USE ONLY - NOT FOR FINANCE PURPOSES.

NB: INTERNAL USE ONLY - NOT FOR FINANCE PURPOSES.

ROAD TEST

Performance ✓
 Noise ✓
 Handling ✓
 Transmission ✓
 Clutch ✓

Brakes ✓
 Vibrations ✓
 Wheel Alignment ✓
 Wheel Balancing ✓

BCS DEALERSHIP DECLARATION

I hereby declare that the above mentioned vehicle has been inspected by the Bosch Service dealer and at the time of this application the vehicle was found to be roadworthy and of sound mechanical condition.

Technician Name: Ricardo

Date: 06/10/2025

Signature: [Signature]

Service Advisor/Managers Name: _____
 print name

Signature: _____