

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name:bosch service centre

Address:564 Steve Biko Road

Telephone:0123355737

Email:pieter@boschgezina.co.za

Sn:988579800333

Time:2024-10-10 16:31:17

Technician Name:john

Order no:

Service fee:

Notes:

Vehicle Information

Year:2018

Make:USAFORD

Model:Ranger / Mazda B-Ser

VIN:AFAPXXMJ2PJR47353

Displacement:G 1.0 MPI KAPPA

Odometer:122442 km

Vehicle Software Version:V10.86

Inspection Result

The following systems are OK:

- 1.ABS (Anti-Lock Braking System)
- 2.ACM (Audio Control Module)
- 3.BCMII (Body Control Module)
- 4.FCIM (Front Controls Interface Module)
- 5.GWM (Gateway Module A)
- 6.IPC (Instrument Panel Control Module)
- 7.PCM (Powertrain Control Module)
- 8.PSCM (Power Steering Control Module)
- 9.RCM (Restraint Control Module)
- 10.RTM (Radio Transceiver Module)
- 11.SCCM (Steering Column Control Module)
- 12.TCM (Transmission Control Module)
- 13.TRM (Trailer Module)