

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name:bosch service centre
Address:564 Steve Biko Road
Telephone:0123355737
Email:mariska@boschgezina.co.za
Sn:988579800333
Time:2024-07-19 10:33:00
Technician Name:Ricardo
Order no:
Service fee:
Notes:

Vehicle Information

Year:2018
Make:NISSAN
Model:np200
VIN:ADNUSN365U0147516
Displacement:G 1.0 MPI KAPPA
Odometer:130140 km
Vehicle Software Version:V10.32

Inspection Result

The following systems are OK:

- 1.ENGINE
- 2.ABS
- 3.BCM
- 4.AIR BAG
- 5.EPS/DAST 3