

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name:bosch service centre

Address:564 Steve Biko Road

Telephone:0123355737

Email:pieter@boschgezina.co.za

Sn:988579800333

Time:2024-08-05 08:06:16

Technician Name:Dries

Order no:

Service fee:

Notes:

Vehicle Information

Year:2021

Make:HYUNDAI

Model:Venue(QXI)

VIN:MALFC81AVMM148311

Displacement:G 1.0 T-GDI KAPPA

Odometer:93744 km

Vehicle Software Version:V10.30

Inspection Result

The following systems are OK:

- 1.ECM (Engine Control Module)
- 2.TCM (Transmission Control Module)
- 3.ABS (Anti-lock Braking System)
- 4.Airbag(Event #1)
- 5.Airbag(Event #2)
- 6.AC (Air Conditioning)
- 7.Integrated Body Control Unit-BCM
- 8.Integrated Body Control Unit-SMK
- 9.Integrated Body Control Unit-IMMO
- 10.IC (Cluster Module)
- 11.Integrated Body Control Unit-TPMS
- 12.MDPS (Motor Driven Power Steering)
- 13.ICCU (Integrated Central Control Unit)
- 14.CODE (Transmitter Code Saving)