Make	BMW	
Model	420D COUPE M SPORT A/T (G22)	
Vin	WBA12AS060CG48510	
Engine Specifications	Diesel	
Vehicle Type	C/P	
Service Plan	N/A	

Year	2021
Km	
Transmission	Automatic
Colour	BLUE
Branch	Bosch Car Service
Warranty Plan	N/A

Interior					
Radio / Entertainment	Within Specification	~	Aircon Controls	Within Specification	•
Cluster	Within Specification	~	Electric Windows	Within Specification	•

Exterior					
Windscreen	Within Specification		Mag Wheels	Within Specification	-
Side Mirrors / Electric	Within Specification	lacksquare	Wiper Blades	Within Specification	•

BOSCH VEHICLE INSPECTION					
Engine					
Oil Service		Km	Dip Stick	Within Specification	•
Oil Filter	Within Specification	•	Oil Filler Cap	Within Specification	•
Fuel/Diesel Filter	Within Specification	•	Fan Belt	Not Applicable	•
Air Filter	Within Specification	~	Fan belt Tensioner	Within Specification	•
Cabin Filter	Within Specification	~	Alternator Belt	Within Specification	•
Spark Plugs	Within Specification	~	Power Steering Belt	Within Specification	•
Brake Fluid	Within Specification	~	Aircon Belt	Within Specification	•
Antifreeze	Within Specification	—	Multi V belt	Within Specification	•
Rear Main Seal	Within Specification	~	Engine Mountings	Within Specification	•
Sump/Gasket	Within Specification	~	PCV Valve	Within Specification	•

Braking System		
Front Brake Pads	-Select-	-
Front Brake Discs	Within Specification	
Front Brake Sensor	Within Specification	-
Rear Brake Pads	-Select-	
Rear Brake Discs	Within Specification	-
Rear Brake Sensor	Within Specification	•
Rear Drums	Within Specification	-
Rear Linings	60%	
Brake Master	Within Specification	•
Hand Brake	Within Specification	•
Brake Calipers	Within Specification	
Brake Hose	Within Specification	-

Cooling System		
Radiator	Within Specification	-
Radiator Hoses	Within Specification	•
Waterpump	Within Specification	•
Thermostat	Within Specification	•
Aircon Gas	Within Specification	•
Aircon Pump	Within Specification	•
Aircon Condensor	Within Specification	•
Interior Fan	Within Specification	•
Interior Radiator	Within Specification	•

Fueling System		
Intake Manifold	Within Specification	•
Throttle	Within Specification	V
Turbo	Within Specification	V
Injectors	Within Specification	V
Fuel Pump	Within Specification	•
Fuel Lines	Within Specification	•

Ignition System		
Ignition Coils	Within Specification	—
Glow Plugs	Within Specification	•
Distrubutor	Within Specification	—
HT Leads	Within Specification	•



BOSCH INSPECTION REPORT

Steering & Suspension		
Steering Rack	Within Specification	lacksquare
Power Steering Pump	Within Specification	•
Wheel Alignment	Within Specification	lacksquare
CV Joints	Within Specification	•
CV Boots	Within Specification	lacksquare
Shocks Front	Within Specification	•
Shock Mountings Front	Within Specification	lacksquare
Shocks Rear	Within Specification	lacksquare
Stabilizer Links	Within Specification	V
Wheel Bearings	Within Specification	•
Bearing Hubs	Within Specification	lacksquare
Control Arms	Within Specification	—
Sideshafts/Seal	Within Specification	V
Propshaft	Not Applicable	•
Wheel Nuts/Studs	Within Specification	•
Tyres & Spare	Within Specification	•
Mag Wheels/Hub Caps	Within Specification	•

Transmission & Clutch		
Clutch Kit	Not Applicable	•
Clutch Master	Not Applicable	-
Clutch Slave	Not Applicable	—
Clutch Cable	Not Applicable	—
Gearbox	Within Specification	—
Gear & Diff oil	No Visible Leaks	-
Auto Transmission	Within Specification	-
Gear Selector	Within Specification	-
Gear Linkages	Within Specification	•

Ignition System		
Diagnostics	Within Specification	\
Cyl Leakage Test	Within Specification	\rightarrow
Road Test	Within Specification	~
Handling	Within Specification	\rightarrow

Concluding Remarks		

Bosch Technician	
-Select-	•

General Comments		

NEW Technician	
MIKE JONES	

Date of Inspection	
22-Nov-2024	



