



BOSCH INSPECTION REPORT

BOSCH JC#: _____

Make	BMW	
Model	X4 xDRIVE28i M SPORT	
Vin	WBAXW320700F79547	
Engine Specifications	28i	Petrol <input type="checkbox"/>
Vehicle Type	SUV	
Service Plan	N/A	

Year	2015
Km	110577
Transmission	Automatic <input type="checkbox"/>
Colour	WHITE
Branch	Bosch Car Service
Warranty Plan	N/A

Interior

The interior is in good condition , no visible damages

Radio / Entertainment	In good working order
Cluster	In good working order

Aircon Controls	In good working order
Electric Windows	In good working order

Exterior

No visible damages, minor imperfections may be present

Windscreen	In good working order <input type="checkbox"/>
Side Mirrors / Electric	Within Specification

Mag Wheels	Acceptable for vehicle <input type="checkbox"/>
Wiper Blades	In good working order <input type="checkbox"/>

BOSCH VEHICLE INSPECTION

Engine

Oil Service		Km
Oil Filter	Within Specification <input type="checkbox"/>	
Fuel/Diesel Filter	Very Good <input type="checkbox"/>	
Air Filter	No Fault Codes <input type="checkbox"/>	
Cabin Filter	No Fault Codes <input type="checkbox"/>	
Spark Plugs	Within Specification <input type="checkbox"/>	
Brake Fluid	Within Specification <input type="checkbox"/>	Clean & free of contaminants
Antifreeze	Very Good	Level ok with required coolant ratio
Rear Main Seal	No Leaks	
Sump/Gasket	No Leaks	
Dip Stick	Within Specification	



BOSCH INSPECTION REPORT

BOSCH JC#: _____

Oil Filler Cap	No Leaks		Sealed with no leaks
Fan Belt	Within Specification	<input type="checkbox"/>	
Fan belt Tensioner	Very Good	<input type="checkbox"/>	No noise from tensioner
Alternator Belt	Within Specification	<input type="checkbox"/>	
Power Steering Belt	Very Good	<input type="checkbox"/>	
Aircon Belt	Within Specification	<input type="checkbox"/>	
Multi V belt	Very Good	<input type="checkbox"/>	
Engine Mountings	Within Specification		
PCV Valve	Within Specification		Working as per manufacturers specification

Braking System		
Front Brake Pads	Very Good	80 %
Front Brake Discs	Within Specification	
Front Brake Sensor	Within Specification	
Rear Brake Pads	Very Good	70 %
Rear Brake Discs	Very Good	
Rear Brake Sensor	Very Good	
Rear Drums	Not Applicable	<input type="checkbox"/>
Rear Linings	Not Applicable	<input type="checkbox"/>
Brake Master	Within Specification	
Hand Brake	Not Applicable	<input type="checkbox"/>
Brake Calipers	Within Specification	
Brake Hose	Very Good	

Cooling System		
Radiator	No Leaks	
Radiator Hoses	No Leaks	
Waterpump	No Leaks	
Thermostat	No Leaks	
Aircon Gas	Very Good	
Aircon Pump	No Leaks	
Aircon Condensor	Very Good	
Interior Fan	Very Good	
Interior Radiator	Within Specification	

Fueling System		
Intake Manifold	No Leaks	
Throttle	Within Specification	
Turbo	Within Specification	<input type="checkbox"/>
Carburetor	Not Applicable	
Injectors	Very Good	<input type="checkbox"/>
Fuel Pump	Within Specification	
Fuel Lines	No Leaks	

Ignition System		
Ignition Coils	Within Specification	
Glow Plugs	Not Applicable	<input type="checkbox"/>
Distributor	Not Applicable	
HT Leads	Not Applicable	



BOSCH INSPECTION REPORT

BOSCH JC#: _____

Steering & Suspension	
Steering Rack	Within Specification
Power Steering Pump	Within Specification <input type="checkbox"/>
Wheel Alignment	Within Specification
CV Joints	Very Good
CV Boots	Very Good
Shocks Front	No Leaks
Shock Mountings Front	Very Good
Shocks Rear	No Leaks
Stabilizer Links	Very Good
Wheel Bearings	Within Specification
Bearing Hubs	Within Specification
Control Arms	Within Specification
Sideshafts/Seal	No Fault Codes <input type="checkbox"/>
Propshaft	Within Specification <input type="checkbox"/>
Wheel Nuts/Studs	Very Good
Tyres & Spare	Within Specification
Mag Wheels/Hub Caps	Very Good

Transmission & Clutch	
Clutch Kit	Not Applicable <input type="checkbox"/>
Clutch Master	Not Applicable <input type="checkbox"/>
Clutch Slave	Not Applicable <input type="checkbox"/>
Clutch Cable	Not Applicable
Gearbox	Not Applicable <input type="checkbox"/>
Gear & Diff oil	Not Applicable <input type="checkbox"/>
Auto Transmission	Not Applicable <input type="checkbox"/>
Gear Selector	Not Applicable <input type="checkbox"/>
Gear Linkages	Not Applicable <input type="checkbox"/>

Ignition System	
Diagnostics	Very Good
Cyl Leakage Test	Very Good <input type="checkbox"/>
Test Drive	Very Good
Handling	Very Good

Final Notes & Comments

This vehicle inspection has been done impartially and to the best of our knowledge. This Bosch Inspection Report has been applied to all above items and are based the visual inspection and functionality thereof. Bosch cannot be held responsible for any unforeseen or concealed defects. The road test done within the confines of the inspection location. The vehicle is void of visual leaks or engine sludge build up and the vehicle is performing within acceptable and roadworthy conditions

Bosch Technician	
Basal Johnson	<input type="checkbox"/>

Date of Inspection
2014-12-20



BOSCH CAR SERVICE PRETORIA

a: 564 Steve Biko Road, Gezina, Pretoria 0084
 t: 012 335 5737
 e: reception@boschgezina.co.za



AC-MI4006060