

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name:bosch service centre

Address:564 Steve Biko Road

Telephone:0123355737

Email:karika@boschgezina.co.za

Sn:988579800333

Time:11/11/2024 14:12:47

Technician Name:shaun

Vehicle Information

Make:SUZUKI

VIN:TSMJYA22S00148989

Displacement:G 1.4 DOHC

Odometer:112030 km

Vehicle Software Version:V10.36

Inspection Result

The following systems are OK:

- 1.ECM (Engine Control Module)
- 2.TCM (Transmission Control Module)
- 3.ABS (Anti-Lock Braking System)
- 4.EPS (Electronic Power Steering)
- 5.SRS (Supplemental Inflatable Restraint System/Airbag)
- 6.AC (Air Conditioning)
- 7.BCM (Body Control Module)
- 8.KLS (Keyless Start)
- 9.IPC (Combination Meter / Meter/ M&A)
- 10.ALC (Headlight Auto Leveling)