

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name:

Address:

Telephone:N/A

Sn:988579800333

Time:06/20/2025 16:16:07

Technician Name:RICARDO

Vehicle Information

Make:BMW

Model:X1 sDrive18i

VIN:WBAJG12090EN48999

Displacement:G 1.0 MPI KAPPA

Odometer:78664 km

Vehicle Software Version:V10.62

Inspection Result

The following systems are OK:

- 1.ACSM (Crash safety module - SRS)
- 2.TRSVC (allround-view camera)
- 3.HKFM (Tailgate function module)
- 4.ZGM (Central Gateway Module)
- 5.DME/DDE (Digital Engine Electronics - ECM)
- 6.EGS (Electronic transmission management - TCM)
- 7.DSC (Dynamic stability control - ABS)
- 8.PMA (parking assistant)
- 9.EPS (Electromechanical power steering)
- 10.BDC (Body Domain Controller)
- 11.FLEL (Frontal Light Electronics Left)
- 12.FLER (Frontal Light Electronics Right)
- 13.FZD (Roof function centre)
- 14.GWS (Gear selector switch)
- 15.KOMBI (Instrument panel)
- 16.TCB (Telematic Communication Box)
- 17.HU-B (HU-B)
- 18.CON (Controller)
- 19.IHKA (Integrated automatic heating / air conditioning system)