

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name:bosch service centre
Address:564 Steve Biko Road
Telephone:0123355737
Email:juan-dre@boschgezina.co.za
Sn:988579800333
Time:2024-08-30 11:11:14
Technician Name:shaun
Order no:
Service fee:
Notes:

Vehicle Information

Year:2016
Make:VW
VIN:AAVZZZ6RZGU050259
Displacement:G 1.6 MPI
Odometer:108485 km
Vehicle Software Version:V10.23

Inspection Result

The following systems are OK:

- 1.01 Engine Electronics
- 2.03 Brake Electronics
- 3.08 Climate Control Module
- 4.09 Electronic Central Electric
- 5.15 Airbag
- 6.17 Instrument Cluster
- 7.19 Data Bus OBD Interface
- 8.44 Power Steering
- 9.5F Information Electronics 1