

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name:bosch service centre

Address:564 Steve Biko Road

Telephone:0123355737

Email:pieter@boschgezina.co.za

Sn:988579800333

Time:2024-08-15 08:31:44

Technician Name:Ricardo

Order no:

Service fee:

Notes:

Vehicle Information

Year:2015

Make:TOYOTA

Model:Hilux

VIN:AHTEB6CB702505900

Displacement:G 1.6 GDI GAMMA

Odometer:136040.00 km

Vehicle Software Version:V10.44

Inspection Result

The following systems are OK:

1.EOBD/OBD II

2.ECMECT (Engine and ECT)

3.CCS (Cruise Control)

4.ABS (Anti-lock Braking System)/VSC (Vehicle Stability Control)/TRC (Traction Control System)

5.SRS (Supplemental Inflatable Restraint System)

6.CM (Combination Meter)