

# All System Diagnostic Report

The Report is created by **THINKCAR**

## Repair Shop

Shop Name: citton cars  
Address: 564 Steve Biko Road  
Telephone: 0123355737  
Email: johan@boschgezina.co.za  
Sn: 988579800333  
Time: 2023-12-11 16:30:07  
Technician Name: Raymond  
Customer Name: citton cars

## Vehicle Information

Make: BENZ  
VIN: WDC2539892F554805  
Displacement: G 1.4 MPI  
Odometer: 78189 km  
Vehicle Software Version: V10.54

## Inspection Result

The following systems are OK:

1. PTCU - Drivetrain
2. FSCU - Fuel Pump
3. ECM - Engine Control Module (ME)
4. TCM - Transmission Control Module
5. ADS - Adaptive Damping System
6. AMG DRVU - AMG DRIVE UNIT
7. EFB - Electric Parking Brake
8. ES - Electrical Power Steering
9. ESP - Electronic Stability Program
10. AIRMATIC PLUS
11. KAB - Camera Cover
12. MFK - Multifunction Camera
13. PTS - PARKTRONIC
14. SG-AWF - COLLISION PREVENTION ASSIST
15. SGR - Radar Sensors Control Unit
16. 360 Degree Camera - 360 Degree Camera
17. TPM - Tire Pressure Monitor
18. ATA - Interior Motion Sensor
19. EZS - Electronic Ignition Lock
20. SG-SW\_L - Left Headlamp
21. SG-SW\_R - Right Headlamp
22. KG - KEYLESS GO
23. SCM - Steering Column Module
24. RevETR\_LF - Left Front Reversible Emergency Tensioning Retractor
25. RevETR\_RF - Right Front Reversible Emergency Tensioning Retractor

- 26.Driver-side SAM - Front Signal Acquisition And Actuation Module
- 27.REAR SAM - Rear Signal Acquisition And Actuation Module
- 28.SD - Control Module Sliding Roof
- 29.SRS - Supplemental Restraint System
- 30.AHE - Trailer Recognition
- 31.Control unit for telematics services
- 32.COUI[ZBE] - Audio/COMAND Operating Unit
- 33.ZAN - Audio/COMAND Display
- 34.Audio - Audio Or COMAND
- 35.HUD - Head - Up Display
- 36.IC - Instrument Cluster
- 37.SG-MSND - Engine Sound
- 38.SOUND - Sound System
- 39.TPAD - Touchpad
- 40.ESA\_DR - Electric Seat Adjustment Driver
- 41.ESA Front Passenger - Electric Seat Adjustment Front Passenger
- 42.HKS - Tailgate Control
- 43.DCU\_RF - Right Front Door
- 44.DCU\_LF - Left Front Door
- 45.DCU\_LR - Left Rear Door
- 46.DCU\_RR - Right Rear Door
- 47.AC - Air Conditioning