

Client Copy

Citton Cars Inspection Certificate

BATTERY DETAILS

± Age 2019
 Make Volvo XC90 No. _____

Registration No: HV24WSGP

Job Card No: 82053



SERVICE	OK	Not Ok	Rectified	BREAKING SYSTEM	OK	Not Ok	Rectified	STEERING SYSTEM	OK	Not Ok	Rectified		
1 Service				50 Brake Fluid	Cl			100 Ball Joints					
2 Spark Plugs	N/A			51 Disc Pads Front	4 mm			101 Tie Rod Ends					
3 Points & Condenser	N/A			52 Pad Sensors Front				102 Control Arm					
4 Oil				53 Discs Front	mm			103 Drag Link					
5 Oil Filter				54 Brake Caliper				104 Stabiliser Arm					
6 Fuel Filter				55 Brake Caliper Leak(s)				DRIVE LINE			OK	Not Ok	Rectified
7 Air Filter				56 Disc Pads Rear	mm			105 Side Shaft Oil Leak(s)					
8 Pollen Filter				57 Pad Sensors Rear				106 Front Wheel Bearings					
9 Other Filter(s)				58 Drums Rear	mm			107 Front Bearing Hubs					
10 Wiper Blades				59 Disc Rear	mm			108 Rear Wheel Bearings					
11 Windscreen Washers				60 Rear Linings	mm			109 Rear Wheel Bearing Hubs					
12 Pedal Rubbers				61 Rear Cylinders				110 CV Shafts					
ADDITIVES MISC				62 Rear Cylinder Leak(s)				111 CV Boots					
13 Brake Cleaner				63 Handbrake Uning	mm			112 Shocks					
14 Radiator Flush				64 Handbrake Cable				113 Springs					
15 Carb Cleaner				65 Brake Master Cylinder				114 Shock Mountings					
16 Engine Flush				66 Master Cylinder Leak(s)				115 Wheel Nuts/Studs					
TRANSMISSION				67 ABS System				116 Tyres & Spare Pressure					
17 Transmission				68 Brake Hoses				117 Tyres & Spare Condition					
18 Transmission Oil				CLUTCH SYSTEM			OK	Not Ok	Rectified				
19 Transmission Oil Leak(s)				69 Clutch Fluid	Cl			118 Grease Points					
20 Transfer Box				70 Clutch Operation				119 Prop Shaft(s)					
21 Transfer Box Oil	N/A			71 Clutch Master				EXHAUST SYSTEM			OK	Not Ok	Rectified
22 Transfer Box air Leak(s)	N/A			72 Clutch Master Leak				120 Exhaust Silencer					
23 Differential				73 Clutch Slave				121 Catalytic Converter					
24 Differential Oil				74 Clutch Slave Leak	Cl			122 Flange Gasket					
25 Differential Oil Leak(s)				75 Clutch Cable				123 Exhaust Manifold Gasket					
26 Differential Lock				COOLING SYSTEM			OK	Not Ok	Rectified				
27 Differential Mounting(s)				76 Water Leaks				124 Turbo Gasket(s)					
28 Transmission Mounting				77 Reservoir Bottle				125 Hangers					
ENGIN				78 Antifreeze	Cl			ELECTRICAL			OK	Not Ok	Rectified
29 Engine Oil Leak(s)				79 Cooling Fan				126 ECU					
30 Oil Filler Cap				80 Radiator Hoses				127 Headlights - Dim					
31 Cam Belt	chain			81 Water Pump				128 Headlights - Bright					
32 Cam Belt Tensioner				82 Thermostat				129 Fog Lights					
33 Drive Belt(s) / V-Belt(s)				83 Radiator				130 Brake Lights					
34 Tensioner/Pulleys				84 Cooling System Pressure Test				131 Park Lights					
35 Hydraulic Lifters				85 Hose Clamps				132 Dash Lights					
36 Tappet Noise				86 Radiator Cap				133 Interior Lights					
37 Throttle Assembly				87 Cap Pressure Test				134 Ficker Lights Left					
38 Turbo				IGNITION SYSTEM			OK	Not Ok	Rectified				
39 Carburetor	N/A			88 Coil(s)				135 Ficker Lights Right					
40 Injectors				89 Distributor				136 Spot Lights					
41 Fuel Pump				90 Distributor Cap				137 Reverse Light(s)					
42 Fuel Line				91 Rotor				138 Starter					
43 Vacuum System				92 High Tension Leads				139 Alternator					
44 Relative Compression Test				STEERING SYSTEM			OK	Not Ok	Rectified				
45 Engine Mounting				93 Steering System				140 Battery					
AIR CONDITIONER				94 Steering System Leak(s)				141 Battery Terminals					
46 Climate Control				95 Power Steering Pump				142 Battery Water					
47 Climate Temp	Cl			96 Power Steering Fluid				143 Power Windows					
48 Compressor				97 Power Steering Pipes				144 Side Mirrors					
49 Service Air-Con System				98 Steering Boots				145 Instrument					
				99 Steering Rack				146 Sensors					
								147 Seat Belts					
								148 Seats					
								149 Diagnostic Check					
								150 Hooter					

NB: INTERNAL USE ONLY - NOT FOR FINANCE PURPOSES.

NB: INTERNAL USE ONLY - NOT FOR FINANCE PURPOSES.

ROAD TEST				
Performance		See done at 14-09-2023 81270	Brakes	
Noise			Vibrations	
Handling			Wheel Alignment	
Transmission			Wheel Balancing	
Clutch				
				Tool in Boot

BCS DEALERSHIP DECLARATION

I hereby declare that the above mentioned vehicle has been inspected by the Bosch Service dealer and at the time of this application the vehicle was found to be roadworthy and of sound mechanical condition.

Technician Name: Bosch

Date: 12-10-2023

Signature: [Signature]

Service Advisor/Managers Name: _____
print name

Signature: _____