

Full Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name:Citton service center
Address:564 swemmer street , Gezina , Pretoria
Telephone:012335573
Email:karika@boschgezina.co.za
SN:988579800333
Test Time:11/20/2023 13:09:55
Technician Name:Justice

Vehicle Information

Year:2016.09
Vehicle brand:BMW
Model:X1 xDrive20i
VIN:WBAHS920505G63727
Odometer:119383 km
Vehicle Software Version:V10.26



Inspection Result

FZD (Function Center, Roof) 1 problems exist

1.030295 Sliding Trim: No Initialisation Present

The following systems are OK:

- 1.SRS (Supplemental Inflatable Restraint System - AIRBAG/SGM-SIM)
- 2.ZGM (Central Gateway Module)
- 3.ECM (Engine Control Module - DME/DDE)
- 4.TCM (Transmission Control Module - EGS)
- 5.LMV/VTG (Transfer Case)
- 6.ABS (Anti-Lock Braking System - DSC)
- 7.PMA (Parking Assistant)
- 8.EPS (Electronic Power Steering)
- 9.CAS (Car Access System - CAS/FEM/BDC)
- 10.LHML (LED Main Light Module, Left)
- 11.LHMR (LED Main Light Module, Right)
- 12.IC (Instrument Cluster - INSTR)
- 13.ECALL (Emergency Call)
- 14.CIC (Car Information Computer)
- 15.ZBE/CON (Controller)
- 16.AC (Air Conditioning - IHKA)