



| | | |
|-----------------------|-------------------|--------|
| Make | mahindra | |
| Model | XUV500 | |
| Vin | MA1YV2HKUH6059133 | |
| Engine Specifications | 2.2D | Diesel |
| Vehicle Type | SUV | |
| Service Plan | N/A | |

| | |
|---------------|-------------------|
| Year | 2016 |
| Km | 130732 |
| Transmission | Manual |
| Colour | GREY |
| Branch | Bosch Car Service |
| Warranty Plan | N/A |

Interior

The interior is in good condition , no visible damages

| | |
|-----------------------|-----------------------|
| Radio / Entertainment | In good working order |
| Cluster | In good working order |

| | |
|------------------|-----------------------|
| Aircon Controls | In good working order |
| Electric Windows | In good working order |

Exterior

No visible damages, minor imperfections may be present

| | |
|-------------------------|----------------------|
| Windscreen | No visible damages |
| Side Mirrors / Electric | Within Specification |

| | |
|--------------|-----------------------|
| Mag Wheels | No visible damages |
| Wiper Blades | In good working order |

BOSCH VEHICLE INSPECTION

Engine

| | | |
|--------------------|----------------------|--------------------------------------|
| Oil Service | 2023-12-06 | 130732 Km |
| Oil Filter | Within Specification | |
| Fuel/Diesel Filter | Within Specification | |
| Air Filter | Within Specification | |
| Cabin Filter | Within Specification | |
| Spark Plugs | Not Applicable | |
| Brake Fluid | Very Good | Clean & free of contaminants |
| Antifreeze | Very Good | Level ok with required coolant ratio |
| Rear Main Seal | No Leaks | |
| Sump/Gasket | No Leaks | |
| Dip Stick | Within Specification | |



| | | |
|---------------------|----------------------|--|
| Oil Filler Cap | No Leaks | Sealed with no leaks |
| Fan Belt | Within Specification | |
| Fan belt Tensioner | Very Good | No noise from tensioner |
| Alternator Belt | Within Specification | |
| Power Steering Belt | Not Applicable | |
| Aircon Belt | Within Specification | |
| Multi V belt | Within Specification | |
| Engine Mountings | Within Specification | |
| PCV Valve | Within Specification | Working as per manufacturers specification |

| Braking System | | |
|--------------------|----------------------|-------|
| Front Brake Pads | Very Good | 100 % |
| Front Brake Discs | Within Specification | |
| Front Brake Sensor | Not Applicable | |
| Rear Brake Pads | Very Good | 85 % |
| Rear Brake Discs | Very Good | |
| Rear Brake Sensor | Not Applicable | |
| Rear Drums | Not Applicable | |
| Rear Linings | Not Applicable | |
| Brake Master | Within Specification | |
| Hand Brake | Within Specification | |
| Brake Calipers | Within Specification | |
| Brake Hose | Very Good | |

| Cooling System | | |
|-------------------|----------------------|--|
| Radiator | No Leaks | |
| Radiator Hoses | No Leaks | |
| Waterpump | No Leaks | |
| Thermostat | No Leaks | |
| Aircon Gas | Very Good | |
| Aircon Pump | No Leaks | |
| Aircon Condensor | Very Good | |
| Interior Fan | Very Good | |
| Interior Radiator | Within Specification | |

| Fueling System | |
|-----------------|----------------------|
| Intake Manifold | No Leaks |
| Throttle | Within Specification |
| Turbo | Not Applicable |
| Carburetor | Not Applicable |
| Injectors | No Fault Codes |
| Fuel Pump | Within Specification |
| Fuel Lines | No Leaks |

| Ignition System | |
|-----------------|----------------|
| Ignition Coils | Not Applicable |
| Glow Plugs | Not Applicable |
| Distributor | Not Applicable |
| HT Leads | Not Applicable |



| Steering & Suspension | |
|-----------------------|----------------------|
| Steering Rack | Within Specification |
| Power Steering Pump | No Leaks |
| Wheel Alignment | Within Specification |
| CV Joints | Very Good |
| CV Boots | Very Good |
| Shocks Front | No Leaks |
| Shock Mountings Front | Very Good |
| Shocks Rear | No Leaks |
| Stabilizer Links | Very Good |
| Wheel Bearings | Within Specification |
| Bearing Hubs | Within Specification |
| Control Arms | Within Specification |
| Sideshafts/Seal | No Leaks |
| Propshaft | Not Applicable |
| Wheel Nuts/Studs | Very Good |
| Tyres & Spare | Very Good |
| Mag Wheels/Hub Caps | Very Good |

| Transmission & Clutch | |
|-----------------------|----------------------|
| Clutch Kit | Within Specification |
| Clutch Master | Within Specification |
| Clutch Slave | Within Specification |
| Clutch Cable | Not Applicable |
| Gearbox | Within Specification |
| Gear & Diff oil | Not Applicable |
| Auto Transmission | Not Applicable |
| Gear Selector | Very Good |
| Gear Linkages | Very Good |

| Ignition System | |
|------------------|----------------------|
| Diagnostics | Within Specification |
| Cyl Leakage Test | No Leaks |
| Test Drive | Very Good |
| Handling | Very Good |

Final Notes & Comments

This vehicle inspection has been done impartially and to the best of our knowledge. This Bosch Inspection Report has been applied to all above items and are based the visual inspection and functionality thereof. Bosch cannot be held responsible for any unforeseen or concealed defects. The road test done within the confines of the inspection location. The vehicle is void of visual leaks or engine sludge build up and the vehicle is performing within acceptable and roadworthy conditions.

Bosch Technician

Dries Olwagen

Date of Inspection

2023-12-06



BOSCH CAR SERVICE PRETORIA

a: 564 Steve Biko Road, Gezina, Pretoria 0084
 t: 012 335 5737
 e: reception@boschgezina.co.za



AC-MI4006060