

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name:N/A
Address:N/A N/A
Telephone:N/A
Sn:988579800333
Time:2023-11-29 16:34:46

Vehicle Information

Make:Volvo
VIN:YV1DZA8CDG2911854
Displacement:G 1.0 T-GDI KAPPA
Odometer:108639 km
Vehicle Software Version:V10.16

Inspection Result

The following systems are OK:

- 1.AUD (Audio Module)
- 2.CCM (Climate Control Module)
- 3.DDM (Driver Door Module)
- 4.KVM (Keyless Vehicle Module)
- 5.PAC (Parking Assistance Camera)
- 6.PDM (Passenger Door Module)
- 7.POT (Power Operated Tailgate Module)
- 8.PSM (Power Seat Module)
- 9.ICM (Infotainment Control Module)
- 10.ABS (Anti-Lock Braking System)
- 11.CEM (Central Electrical Module)
- 12.CVM (Closing Velocity Module)
- 13.DIM (Driver Information Module)
- 14.PAM (Park Assist Module)
- 15.PBM (Park Brake Module)
- 16.SAS (Steering Wheel Angle Sensor Module)
- 17.SRS (Supplemental Inflatable Restraint System)
- 18.TCM (Transmission Control Module)
- 19.DIESEL ENG (Fuel System/Combined System)
- 20.PSCM (Power Steering Control Module)