

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name: Bosch Car Service Pretoria
Address: 564 Steve Biko Road
Telephone: 0123355737
Email: karika@boschgezina.co.za
Sn: 988579800333
Time: 2023-11-24 07:24:12
Technician Name: Adriaan

Vehicle Information

Make: AUDI
Model: A5
VIN: WAUZZZF55JA057128
Odometer: 53982 miles
Vehicle Software Version: V10.22

Inspection Result

- The following systems are OK:
- 1.01 Engine Electronics
 - 2.02 Transmission Electronics
 - 3.03 Brake Electronics
 - 4.08 Climate Control Module
 - 5.09 Electronic Central Electric
 - 6.15 Airbag
 - 7.16 Steering Column Electronics Systems
 - 8.17 Instrument Cluster
 - 9.19 Data Bus OBD Interface
 - 10.29 Left Light Control
 - 11.39 Right Light Control
 - 12.42 Driver's Door Electronics
 - 13.44 Power Steering
 - 14.46 Comfort System Central Control Module
 - 15.52 Passenger's Door Electronics
 - 16.5F Information Electronics 1
 - 17.81 Selector Lever
 - 18. CA Sunroof Control Module