



Make	KIA	
Model	SPORTAGE 2.0 IGNITE	
Vin	U5YPG81ALHL182062	
Engine Specifications	2.0	Petrol <input type="checkbox"/>
Vehicle Type	SUV	
Service Plan	N/A	

Year	2017	
Km	126404	
Transmission	Manual	<input type="checkbox"/>
Colour	RED	
Branch	Bosch Car Service	
Warranty Plan	N/A	

## Interior

The interior is in good condition , no visible damages

Radio / Entertainment	In good working order	<input type="checkbox"/>	Aircon Controls	In good working order
Cluster	No visible damages	<input type="checkbox"/>	Electric Windows	In good working order

## Exterior

No visible damages, minor imperfections may be present

Windscreen	In good working order	<input type="checkbox"/>	Mag Wheels	No visible damages	<input type="checkbox"/>
Side Mirrors / Electric	Within Specification	<input type="checkbox"/>	Wiper Blades	In good working order	<input type="checkbox"/>

## BOSCH VEHICLE INSPECTION

### Engine

Oil Service		2023-09-27		126183 Km
Oil Filter	-Select-	<input type="checkbox"/>		
Fuel/Diesel Filter	-Select-	<input type="checkbox"/>		
Air Filter	Very Good	<input type="checkbox"/>		
Cabin Filter	Within Specification	<input type="checkbox"/>		
Spark Plugs	Within Specification	<input type="checkbox"/>		
Brake Fluid	No Leaks	<input type="checkbox"/>	Clean & free of contaminants	
Antifreeze	No Leaks	<input type="checkbox"/>	Level ok with required coolant ratio	
Rear Main Seal	No Leaks	<input type="checkbox"/>		
Sump/Gasket	No Leaks	<input type="checkbox"/>		
Dip Stick	Very Good	<input type="checkbox"/>		



Oil Filler Cap	Very Good	<input type="checkbox"/>	Sealed with no leaks
Fan Belt	-Select-	<input type="checkbox"/>	
Fan belt Tensioner	Very Good	<input type="checkbox"/>	No noise from tensioner
Alternator Belt	Very Good	<input type="checkbox"/>	
Power Steering Belt	Not Applicable	<input type="checkbox"/>	
Aircon Belt	Very Good	<input type="checkbox"/>	
Multi V belt	Very Good	<input type="checkbox"/>	
Engine Mountings	Very Good	<input type="checkbox"/>	
PCV Valve	No Fault Codes	<input type="checkbox"/>	Working as per manufacturers specification

Braking System			
Front Brake Pads	-Select-	<input type="checkbox"/>	80 %
Front Brake Discs	Within Specification	<input type="checkbox"/>	
Front Brake Sensor	Not Applicable	<input type="checkbox"/>	
Rear Brake Pads	Renewed	<input type="checkbox"/>	100 %
Rear Brake Discs	Within Specification	<input type="checkbox"/>	
Rear Brake Sensor	Not Applicable	<input type="checkbox"/>	
Rear Drums	Within Specification	<input type="checkbox"/>	
Rear Linings	Within Specification	<input type="checkbox"/>	
Brake Master	No Leaks	<input type="checkbox"/>	
Hand Brake	Within Specification	<input type="checkbox"/>	
Brake Calipers	No Leaks	<input type="checkbox"/>	
Brake Hose	No Leaks	<input type="checkbox"/>	

Cooling System			
Radiator	No Leaks	<input type="checkbox"/>	
Radiator Hoses	No Leaks	<input type="checkbox"/>	
Waterpump	Within Specification	<input type="checkbox"/>	
Thermostat	Within Specification	<input type="checkbox"/>	
Aircon Gas	Within Specification	<input type="checkbox"/>	
Aircon Pump	No Fault Codes	<input type="checkbox"/>	
Aircon Condensor	No Leaks	<input type="checkbox"/>	
Interior Fan	Within Specification	<input type="checkbox"/>	
Interior Radiator	No Leaks	<input type="checkbox"/>	

Fueling System			
Intake Manifold	Within Specification	<input type="checkbox"/>	
Throttle	Within Specification	<input type="checkbox"/>	
Turbo	Not Applicable	<input type="checkbox"/>	
Carburetor	Not Applicable	<input type="checkbox"/>	
Injectors	No Fault Codes	<input type="checkbox"/>	
Fuel Pump	No Fault Codes	<input type="checkbox"/>	
Fuel Lines	No Leaks	<input type="checkbox"/>	

Ignition System			
Ignition Coils	No Fault Codes	<input type="checkbox"/>	
Glow Plugs	Not Applicable	<input type="checkbox"/>	
Distributor	Not Applicable	<input type="checkbox"/>	
HT Leads	Not Applicable	<input type="checkbox"/>	



Steering & Suspension		
Steering Rack	No Fault Codes	▼
Power Steering Pump	Not Applicable	▼
Wheel Alignment	Within Specification	▼
CV Joints	Very Good	▼
CV Boots	Very Good	▼
Shocks Front	Very Good	▼
Shock Mountings Front	Very Good	▼
Shocks Rear	Very Good	▼
Stabilizer Links	Very Good	▼
Wheel Bearings	Very Good	▼
Bearing Hubs	Within Specification	▼
Control Arms	-Select-	▼
Sideshafts/Seal	Not Applicable	▼
Propshaft	Not Applicable	▼
Wheel Nuts/Studs	Very Good	▼
Tyres & Spare	-Select-	▼
Mag Wheels/Hub Caps	Very Good	▼

Transmission & Clutch		
Clutch Kit	Renewed	▼
Clutch Master	No Leaks	▼
Clutch Slave	No Leaks	▼
Clutch Cable	Not Applicable	▼
Gearbox	Very Good	▼
Gear & Diff oil	No Leaks	▼
Auto Transmission	Not Applicable	▼
Gear Selector	Very Good	▼
Gear Linkages	Very Good	▼

Ignition System		
Diagnostics	No Fault Codes	▼
Cyl Leakage Test	No Leaks	▼
Test Drive	Very Good	▼
Handling	Very Good	▼

**Final Notes & Comments**

This vehicle inspection has been done impartially and to the best of our knowledge. This Bosch Inspection Report has been applied to all above items and are based the visual inspection and functionality thereof. Bosch cannot be held responsible for any unforeseen or concealed defects. The road test done within the confines of the inspection location. The vehicle is void of visual leaks or engine sludge build up and the vehicle is performing within acceptable and roadworthy conditions

Bosch Technician	
Raymond Mncube	▼

Date of Inspection
2023-12-19



## BOSCH CAR SERVICE PRETORIA

a: 564 Steve Biko Road, Gezina, Pretoria 0084  
 t: 012 335 5737  
 e: reception@boschgezina.co.za



AC-MI4006060