

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name: bosch service centre

Address: 564 Steve Biko Road

Telephone: 0123355737

Email: jaco@boschgezina.co.za

Sn: 988579800333

Time: 2024-07-31 14:55:18

Technician Name: Basal

Customer Name: citton cars

Order no:

Service fee:

Notes:

Vehicle Information

Year: 2017

Make: ROMEO

Model: GIULIA

VIN: ZAREAEN0H7536322

Displacement: G 1.0 MPI KAPPA

Odometer: 102659 km

Vehicle Software Version: V10.72

Inspection Result

The following systems are OK:

1. BCM (Body Control Module)
2. RFH (Radio Frequency Hub)
3. TCM (Transmission Control Module)
4. IPC (Instrument Panel Cluster)
5. ECM (Engine Control Module)
6. ESM (Electronic Shifter Module)
7. ACC (Adaptive Cruise Control)
8. EPS (Electric Power Steering)
9. ORC (Occupant Restraint)
10. ABS (Anti-Lock Braking System)
11. HALF (Haptical Lane Feedback)
12. EMCM (Entertainment Multimedia Control Module)
13. ETM (Entertainment Telematic Module)
14. HVAC (Heating Ventilation Air-Conditioning And Cooling)