

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name:citton cars
Address:564 Steve Biko Road
Telephone:0123355737
Email:johan@boschgezina.co.za
Sn:988579800333
Time:2023-12-22 14:39:59
Technician Name:Ricardo
Customer Name:citton cars

Vehicle Information

Year:2019
Make:VW
Model:golf
VIN:WWZZZAUZKP050105
Odometer:98152 km
Vehicle Software Version:V10.20

Inspection Result

The following systems are OK:

- 1.01 Engine Electronics
- 2.03 Brake Electronics
- 3.08 Climate Control Module
- 4.09 Electronic Central Electric
- 5.15 Airbag
- 6.17 Instrument Cluster
- 7.19 Data Bus OBD Interface
- 8.42 Driver's Door Electronics
- 9.44 Power Steering
- 10.52 Passenger's Door Electronics
- 11.5F Information Electronics 1
- 12.76 Parking Aid