

Engine

# **BOSCH INSPECTION REPORT**

JOB CARD NUMBER 17773

Make	MAZDA	
Model	CX-5 2.0 ACTIVE A/T	
Vin	JM6KF2W7AM06538	70
Engine Specifications	2.0	Petrol
Vehicle Type	SUV	
Service Plan	N/A	

Year	2021
Km	28531
Transmission	Automatic
Colour	GREY
Branch	Bosch Car Service
Warranty Plan	N/A

Interior					
Radio / Entertainment	No Fault Code	•	Aircon Controls	No Fault Code	-
Cluster	No Fault Code	•	Electric Windows	No Fault Code	-

Exterior					
Windscreen	Within Specification	•	Mag Wheels	Within Specification	•
Side Mirrors / Electric	No Fault Code	•	Wiper Blades	Within Specification	-

## **BOSCH VEHICLE INSPECTION**

Oil ServiceKmDip StickWithin SpecificationOil FilterNo Visible LeaksIOil Filter CapWithin SpecificationIFuel/Diesel FilterNot ApplicableIFan BeltNot ApplicableIAir FilterWithin SpecificationIFan belt TensionerWithin SpecificationICabin FilterWithin SpecificationIAlternator BeltNo CracksISpark PlugsNo Fault CodeIPower Steering BeltNot ApplicableIBrake FluidNo Visible LeaksIMulti V beltNo CracksIRear Main SealNo Visible LeaksIEngine MountingsWithin SpecificationISump/GasketNo Visible LeaksIPCV ValveWithin SpecificationI						
Fuel/Diesel Filter       Not Applicable <ul> <li>Fan Belt</li> <li>Not Applicable</li> </ul> Air Filter       Within Specification <ul> <li>Fan belt Tensioner</li> <li>Within Specification</li> <li>Alternator Belt</li> <li>Not Applicable</li> </ul> <ul> <li>Alternator Belt</li> <li>Not Applicable</li> </ul> <ul> <li>Spark Plugs</li> <li>No Fault Code</li> <li>Power Steering Belt</li> <li>No Cracks</li> </ul> <ul> <li>Aircon Belt</li> <li>No Cracks</li> <li>Multi V belt</li> <li>No Cracks</li> <li>Multi V belt</li> </ul> Rear Main Seal     No Visible Leaks <ul> <li>Ingine Mountings</li> <li>Within Specification</li> </ul>	Oil Service		Km	Dip Stick	Within Specification	-
Air FilterWithin SpecificationImage: ConstructionFan belt TensionerWithin SpecificationImage: ConstructionCabin FilterWithin SpecificationImage: ConstructionImage: ConstructionImage: ConstructionImage: ConstructionImage: ConstructionSpark PlugsNo Fault CodeImage: ConstructionImage: ConstructionImage: ConstructionImage: ConstructionImage: ConstructionBrake FluidNo Visible LeaksImage: ConstructionImage: ConstructionImage: ConstructionImage: ConstructionAntifreezeNo Visible LeaksImage: ConstructionImage: ConstructionImage: ConstructionImage: ConstructionRear Main SealNo Visible LeaksImage: ConstructionImage: Construction </td <td>Oil Filter</td> <td>No Visible Leaks</td> <td>-</td> <td>Oil Filler Cap</td> <td>Within Specification</td> <td>-</td>	Oil Filter	No Visible Leaks	-	Oil Filler Cap	Within Specification	-
Cabin Filter       Within Specification       Image: Cabin Filter       Alternator Belt       No Cracks       Image: Cabin Filter         Spark Plugs       No Fault Code       Image: Cabin Filter       No Fault Code       Image: Cabin Filter       No Cracks       Image: Cabin Filter         Brake Fluid       No Visible Leaks       Image: Cabin Filter       No Cracks       Image: Cabin Filter       Image: Cabin Filte	Fuel/Diesel Filter	Not Applicable	-	Fan Belt	Not Applicable	-
Spark Plugs       No Fault Code       Image: Spark Plugs       Not Applicable         Brake Fluid       No Visible Leaks       Image: Spark Plugs       Not Applicable         Antifreeze       No Visible Leaks       Image: Spark Plugs       No Cracks       Image: Spark Plugs         Rear Main Seal       No Visible Leaks       Image: Spark Plugs       Image: Spark Plugs       No Cracks       Image: Spark Plugs	Air Filter	Within Specification	-	Fan belt Tensioner	Within Specification	-
Brake Fluid     No Visible Leaks     Image: Constraint of the const	Cabin Filter	Within Specification	-	Alternator Belt	No Cracks	-
Antifreeze     No Visible Leaks     Multi V belt     No Cracks       Rear Main Seal     No Visible Leaks     Engine Mountings     Within Specification	Spark Plugs	No Fault Code	-	Power Steering Belt	Not Applicable	•
Rear Main Seal     No Visible Leaks     Engine Mountings     Within Specification	Brake Fluid	No Visible Leaks	-	Aircon Belt	No Cracks	•
	Antifreeze	No Visible Leaks	-	Multi V belt	No Cracks	•
Sump/Gasket No Visible Leaks   PCV Valve Within Specification	Rear Main Seal	No Visible Leaks	-	Engine Mountings	Within Specification	•
	Sump/Gasket	No Visible Leaks	-	PCV Valve	Within Specification	-

# BOSCH INSPECTION REPORT

Braking System		
Front Brake Pads	40%	•
Front Brake Discs	Within Specification	•
Front Brake Sensor	Not Applicable	•
Rear Brake Pads	60%	-
Rear Brake Discs	Within Specification	•
Rear Brake Sensor	Not Applicable	-
Rear Drums	Not Applicable	•
Rear Linings	-Select-	-
Brake Master	No Visible Leaks	-
Hand Brake	No Fault Code	•
Brake Calipers	No Visible Leaks	•
Brake Hose	No Visible Leaks	-

Cooling System		
Radiator	No Visible Leaks	•
Radiator Hoses	No Visible Leaks	•
Waterpump	No Visible Leaks	•
Thermostat	No Visible Leaks	•
Aircon Gas	No Visible Leaks	•
Aircon Pump	No Fault Code	•
Aircon Condensor	No Visible Leaks	•
Interior Fan	No Fault Code	•
Interior Radiator	No Visible Leaks	•

Fueling System		
Intake Manifold	Within Specification	-
Throttle	No Fault Code	•
Turbo	Not Applicable	•
Injectors	No Fault Code	•
Fuel Pump	No Fault Code	•
Fuel Lines	No Visible Leaks	•

Ignition System		
Ignition Coils	No Fault Code	-
Glow Plugs	Not Applicable	•
Distrubutor	Not Applicable	-
HT Leads	Not Applicable	-



## **BOSCH INSPECTION REPORT**

Steering & Suspension		
Steering Rack	Within Specification	•
Power Steering Pump	Not Applicable	•
Wheel Alignment	Within Specification	•
CV Joints	Within Specification	•
CV Boots	Within Specification	•
Shocks Front	No Visible Leaks	•
Shock Mountings Front	Within Specification	•
Shocks Rear	No Visible Leaks	•
Stabilizer Links	Within Specification	•
Wheel Bearings	Within Specification	<ul><li>▼</li></ul>
Bearing Hubs	Within Specification	•
Control Arms	Within Specification	•
Sideshafts/Seal	No Visible Leaks	•
Propshaft	Not Applicable	-
Wheel Nuts/Studs	Within Specification	-
Tyres & Spare	Within Specification	•
Mag Wheels/Hub Caps	Within Specification	•

Transmission & Clutch		
Clutch Kit	Not Applicable	•
Clutch Master	Not Applicable	•
Clutch Slave	Not Applicable	•
Clutch Cable	Not Applicable	•
Gearbox	No Visible Leaks	•
Gear & Diff oil	No Visible Leaks	•
Auto Transmission	No Visible Leaks	•
Gear Selector	Within Specification	•
Gear Linkages	Within Specification	•

Ignition System		
Diagnostics	No Fault Code	-
Cyl Leakage Test	No Visible Leaks	•
Road Test	Within Specification	•
Handling	Within Specification	•

#### **Concluding Remarks**

### Bosch Technician

Dries Olwagen

**NEW Technician** 

## General Comments

Date of Inspection



## BOSCH CAR SERVICE PRETORIA

a: 564 Steve Biko Road, Gezina, Pretoria 0084 t: 012 335 5737 e: reception@boschgezina.co.za

