

# All System Diagnostic Report

The Report is created by **THINKCAR**

## Repair Shop

Shop Name:

Address:

Telephone:N/A

Sn:988579800333

Time:12/18/2024 12:13:14

Technician Name:dries

## Vehicle Information

Year:2021

Make:MAZDA

Model:CX-5

VIN:JM6KF2W7AM0653870

Displacement:G 2.0 MPI

Odometer:28533 km

Vehicle Software Version:V10.38

## Inspection Result

The following systems are OK:

- 1.F\_BCM (Front Body Control Module)
- 2.IC (Instrument Cluster)
- 3.PCM (Powertrain Control Module)
- 4.R\_BCM (Rear Body Control Module)
- 5.RCM (Restraint Control Module)
- 6.TCM (Transmission Control Module)
- 7.ABS (Anti-Lock Brake System)
- 8.AFS/ALM (Adaptive Front Lighting System/Auto Leveling Module)
- 9.EATC#1 (Electronic Air Temperature Controller)
- 10.CMU (Connectivity Master Unit)
- 11.EPB (Electrical Parking Brake)
- 12.EPS (Electronic Power Steering)
- 13.SSU#1 (Start Stop Unit)