



Make	BMW	
Model	320i M SPORT A/T (F30)	
Vin	WBA8A16070NV09841	
Engine Specifications	2.0	Petrol <input type="checkbox"/>
Vehicle Type	S/D	
Service Plan	Not applicable	

Year	2018
Km	94325
Transmission	Automatic <input type="checkbox"/>
Colour	WHITE
Branch	Bosch Car Service
Warranty Plan	Not applicable

## Interior

The interior is in good condition , no visible damages

Radio / Entertainment	In good working order <input type="checkbox"/>	Aircon Controls	In good working order
Cluster	In good working order <input type="checkbox"/>	Electric Windows	In good working order

## Exterior

No visible damages, minor imperfections may be present

Windscreen	No visible damages <input type="checkbox"/>	Mag Wheels	No visible damages <input type="checkbox"/>
Side Mirrors / Electric	Within Specification <input type="checkbox"/>	Wiper Blades	No visible damages <input type="checkbox"/>

## BOSCH VEHICLE INSPECTION

### Engine

Oil Service			Km
Oil Filter	No Leaks <input type="checkbox"/>		
Fuel/Diesel Filter	No Leaks <input type="checkbox"/>		
Air Filter	Within Specification <input type="checkbox"/>		
Cabin Filter	Within Specification <input type="checkbox"/>		
Spark Plugs	Within Specification <input type="checkbox"/>		
Brake Fluid	Within Specification <input type="checkbox"/>	Clean & free of contaminants	
Antifreeze	Within Specification <input type="checkbox"/>	Level ok with required coolant ratio	
Rear Main Seal	No Leaks <input type="checkbox"/>		
Sump/Gasket	No Leaks <input type="checkbox"/>		
Dip Stick	No Leaks <input type="checkbox"/>		



Oil Filler Cap	No Leaks	<input type="checkbox"/>	Sealed with no leaks
Fan Belt	Within Specification	<input type="checkbox"/>	
Fan belt Tensioner	Within Specification	<input type="checkbox"/>	No noise from tensioner
Alternator Belt	Within Specification	<input type="checkbox"/>	
Power Steering Belt	Within Specification	<input type="checkbox"/>	
Aircon Belt	Within Specification	<input type="checkbox"/>	
Multi V belt	Within Specification	<input type="checkbox"/>	
Engine Mountings	Within Specification	<input type="checkbox"/>	
PCV Valve	Within Specification	<input type="checkbox"/>	Working as per manufacturers specification

---

Braking System		
Front Brake Pads	Within Specification	<input type="checkbox"/> %
Front Brake Discs	Within Specification	<input type="checkbox"/>
Front Brake Sensor	Within Specification	<input type="checkbox"/>
Rear Brake Pads	Within Specification	<input type="checkbox"/> %
Rear Brake Discs	Within Specification	<input type="checkbox"/>
Rear Brake Sensor	Within Specification	<input type="checkbox"/>
Rear Drums	Not Applicable	<input type="checkbox"/>
Rear Linings	Not Applicable	<input type="checkbox"/>
Brake Master	Not Applicable	<input type="checkbox"/>
Hand Brake	Within Specification	<input type="checkbox"/>
Brake Calipers	Within Specification	<input type="checkbox"/>
Brake Hose	Within Specification	<input type="checkbox"/>

Cooling System		
Radiator	No Leaks	<input type="checkbox"/>
Radiator Hoses	No Leaks	<input type="checkbox"/>
Waterpump	No Leaks	<input type="checkbox"/>
Thermostat	No Leaks	<input type="checkbox"/>
Aircon Gas	No Leaks	<input type="checkbox"/>
Aircon Pump	No Leaks	<input type="checkbox"/>
Aircon Condensor	No Leaks	<input type="checkbox"/>
Interior Fan	Within Specification	<input type="checkbox"/>
Interior Radiator	No Leaks	<input type="checkbox"/>

---

Fueling System		
Intake Manifold	Within Specification	<input type="checkbox"/>
Throttle	Within Specification	<input type="checkbox"/>
Turbo	Within Specification	<input type="checkbox"/>
Carburetor	Not Applicable	<input type="checkbox"/>
Injectors	Within Specification	<input type="checkbox"/>
Fuel Pump	Within Specification	<input type="checkbox"/>
Fuel Lines	Within Specification	<input type="checkbox"/>

Ignition System		
Ignition Coils	Within Specification	<input type="checkbox"/>
Glow Plugs	Not Applicable	<input type="checkbox"/>
Distributor	Not Applicable	<input type="checkbox"/>
HT Leads	Not Applicable	<input type="checkbox"/>

---



Steering & Suspension		
Steering Rack	No Leaks	▼
Power Steering Pump	No Leaks	▼
Wheel Alignment	Within Specification	▼
CV Joints	No Leaks	▼
CV Boots	No Leaks	▼
Shocks Front	No Leaks	▼
Shock Mountings Front	Within Specification	▼
Shocks Rear	No Leaks	▼
Stabilizer Links	Within Specification	▼
Wheel Bearings	Within Specification	▼
Bearing Hubs	Within Specification	▼
Control Arms	Within Specification	▼
Sideshafts/Seal	No Leaks	▼
Propshaft	Within Specification	▼
Wheel Nuts/Studs	Within Specification	▼
Tyres & Spare	Within Specification	▼
Mag Wheels/Hub Caps	Within Specification	▼

Transmission & Clutch		
Clutch Kit	Not Applicable	▼
Clutch Master	Not Applicable	▼
Clutch Slave	Not Applicable	▼
Clutch Cable	Not Applicable	▼
Gearbox	Within Specification	▼
Gear & Diff oil	Within Specification	▼
Auto Transmission	Within Specification	▼
Gear Selector	Within Specification	▼
Gear Linkages	Within Specification	▼

Ignition System		
Diagnostics	No Fault Codes	▼
Cyl Leakage Test	Within Specification	▼
Test Drive	Within Specification	▼
Handling	Within Specification	▼

**Final Notes & Comments**

This vehicle inspection has been done impartially and to the best of our knowledge. This Bosch Inspection Report has been applied to all above items and are based the visual inspection and functionality thereof. Bosch cannot be held responsible for any unforeseen or concealed defects. The road test done within the confines of the inspection location. The vehicle is void of visual leaks or engine sludge build up and the vehicle is performing within acceptable and roadworthy conditions

Bosch Technician	
-Select-	▼

Date of Inspection
2023-12-29



## BOSCH CAR SERVICE PRETORIA

a: 564 Steve Biko Road, Gezina, Pretoria 0084  
t: 012 335 5737  
e: reception@boschgezina.co.za



AC-MI4006060