

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name:citton cars
Address:564 Steve Biko Road
Telephone:0123355737
Email:jaco@boschgezina.co.za
Sn:988579800333
Time:2023-12-29 07:51:30
Technician Name:Lardus
Customer Name:cittoncars

Vehicle Information

Year:2018.02
Make:BMW
Model:320i
VIN:WBA8A16070NV09841
Displacement:D 1.5 VGT U2
Odometer:94326 km
Vehicle Software Version:V10.26

Inspection Result

The following systems are OK:

- 1.SRS (Supplemental Inflatable Restraint System - AIRBAG/SGM-SIM)
- 2.ZGM (Central Gateway Module)
- 3.ECM (Engine Control Module - DME/DDE)
- 4.TCM (Transmission Control Module - EGS)
- 5.ICM (Integrated Chassis Management)/RLM_2L (Tail Light Module, Inner Left)
- 6.ABS (Anti-Lock Braking System - DSC)
- 7.EPS (Electronic Power Steering)
- 8.CAS (Car Access System - CAS/FEM/BDC)
- 9.LHML (LED Main Light Module, Left)
- 10.LHMR (LED Main Light Module, Right)
- 11.FZD (Function Center, Roof)
- 12.GWS (Gear Selector Switch)
- 13.IC (Instrument Cluster - INSTR)
- 14.ECALL (Emergency Call)
- 15.CIC (Car Information Computer)
- 16.ZBE/CON (Controller)
- 17.FRM (Footwell Module)/TSGFA (Driver Door Control Unit)
- 18.AC (Air Conditioning - IHKA)