



Make	MITSUBISHI	
Model	OUTLANDER 2.4 GLS A/T	
Vin	JMYXTCW5WDU100237	
Engine Specifications	2.4	Petrol <input type="checkbox"/>
Vehicle Type	MPV	
Service Plan	N/A	

Year	2013
Km	116637
Transmission	Automatic <input type="checkbox"/>
Colour	WHITE
Branch	Bosch Car Service
Warranty Plan	N/A

Interior

The interior is in good condition , no visible damages

Radio / Entertainment	In good working order <input type="checkbox"/>	Aircon Controls	In good working order
Cluster	In good working order <input type="checkbox"/>	Electric Windows	In good working order

Exterior

No visible damages, minor imperfections may be present

Windscreen	No visible damages <input type="checkbox"/>	Mag Wheels	No visible damages <input type="checkbox"/>
Side Mirrors / Electric	Within Specification <input type="checkbox"/>	Wiper Blades	In good working order <input type="checkbox"/>

BOSCH VEHICLE INSPECTION

Engine

Oil Service			Km
Oil Filter	Within Specification <input type="checkbox"/>		
Fuel/Diesel Filter	Within Specification <input type="checkbox"/>		
Air Filter	Within Specification <input type="checkbox"/>		
Cabin Filter	Within Specification <input type="checkbox"/>		
Spark Plugs	Within Specification <input type="checkbox"/>		
Brake Fluid	Within Specification <input type="checkbox"/>	Clean & free of contaminants	
Antifreeze	Within Specification <input type="checkbox"/>	Level ok with required coolant ratio	
Rear Main Seal	No Leaks <input type="checkbox"/>		
Sump/Gasket	No Leaks <input type="checkbox"/>		
Dip Stick	No Leaks <input type="checkbox"/>		



Oil Filler Cap	No Leaks	<input type="checkbox"/>	Sealed with no leaks
Fan Belt	Not Applicable	<input type="checkbox"/>	
Fan belt Tensioner	Renewed	<input type="checkbox"/>	No noise from tensioner
Alternator Belt	Not Applicable	<input type="checkbox"/>	
Power Steering Belt	Not Applicable	<input type="checkbox"/>	
Aircon Belt	Not Applicable	<input type="checkbox"/>	
Multi V belt	Renewed	<input type="checkbox"/>	
Engine Mountings	Within Specification	<input type="checkbox"/>	
PCV Valve	Within Specification	<input type="checkbox"/>	Working as per manufacturers specification

Braking System			
Front Brake Pads	Renewed	<input type="checkbox"/>	100 %
Front Brake Discs	Within Specification	<input type="checkbox"/>	
Front Brake Sensor	Not Applicable	<input type="checkbox"/>	
Rear Brake Pads	Renewed	<input type="checkbox"/>	100 %
Rear Brake Discs	Within Specification	<input type="checkbox"/>	
Rear Brake Sensor	Not Applicable	<input type="checkbox"/>	
Rear Drums	Not Applicable	<input type="checkbox"/>	
Rear Linings	Not Applicable	<input type="checkbox"/>	
Brake Master	Within Specification	<input type="checkbox"/>	
Hand Brake	Within Specification	<input type="checkbox"/>	
Brake Calipers	No Leaks	<input type="checkbox"/>	
Brake Hose	No Leaks	<input type="checkbox"/>	

Cooling System			
Radiator	No Leaks	<input type="checkbox"/>	
Radiator Hoses	No Leaks	<input type="checkbox"/>	
Waterpump	No Leaks	<input type="checkbox"/>	
Thermostat	No Leaks	<input type="checkbox"/>	
Aircon Gas	No Leaks	<input type="checkbox"/>	
Aircon Pump	No Leaks	<input type="checkbox"/>	
Aircon Condensor	No Leaks	<input type="checkbox"/>	
Interior Fan	Within Specification	<input type="checkbox"/>	
Interior Radiator	No Leaks	<input type="checkbox"/>	

Fueling System			
Intake Manifold	Within Specification	<input type="checkbox"/>	
Throttle	Within Specification	<input type="checkbox"/>	
Turbo	Not Applicable	<input type="checkbox"/>	
Carburetor	Not Applicable	<input type="checkbox"/>	
Injectors	Within Specification	<input type="checkbox"/>	
Fuel Pump	Within Specification	<input type="checkbox"/>	
Fuel Lines	No Leaks	<input type="checkbox"/>	

Ignition System			
Ignition Coils	Within Specification	<input type="checkbox"/>	
Glow Plugs	Not Applicable	<input type="checkbox"/>	
Distributor	Not Applicable	<input type="checkbox"/>	
HT Leads	Not Applicable	<input type="checkbox"/>	



Steering & Suspension		
Steering Rack	Within Specification	▼
Power Steering Pump	Within Specification	▼
Wheel Alignment	Within Specification	▼
CV Joints	Within Specification	▼
CV Boots	Within Specification	▼
Shocks Front	Within Specification	▼
Shock Mountings Front	Within Specification	▼
Shocks Rear	Within Specification	▼
Stabilizer Links	Within Specification	▼
Wheel Bearings	Within Specification	▼
Bearing Hubs	Within Specification	▼
Control Arms	Within Specification	▼
Sideshafts/Seal	No Leaks	▼
Propshaft	Within Specification	▼
Wheel Nuts/Studs	Within Specification	▼
Tyres & Spare	Within Specification	▼
Mag Wheels/Hub Caps	Within Specification	▼

Transmission & Clutch		
Clutch Kit	Not Applicable	▼
Clutch Master	Not Applicable	▼
Clutch Slave	Not Applicable	▼
Clutch Cable	Not Applicable	▼
Gearbox	Within Specification	▼
Gear & Diff oil	No Leaks	▼
Auto Transmission	Within Specification	▼
Gear Selector	Within Specification	▼
Gear Linkages	Not Applicable	▼

Ignition System		
Diagnostics	No Fault Codes	▼
Cyl Leakage Test	No Leaks	▼
Test Drive	Within Specification	▼
Handling	Within Specification	▼

Final Notes & Comments

This vehicle inspection has been done impartially and to the best of our knowledge. This Bosch Inspection Report has been applied to all above items and are based the visual inspection and functionality thereof. Bosch cannot be held responsible for any unforeseen or concealed defects. The road test done within the confines of the inspection location. The vehicle is void of visual leaks or engine sludge build up and the vehicle is performing within acceptable and roadworthy conditions

Bosch Technician	
Luandre Swanepoel	▼

Date of Inspection
2023-12-27



BOSCH CAR SERVICE PRETORIA

a: 564 Steve Biko Road, Gezina, Pretoria 0084
 t: 012 335 5737
 e: reception@boschgezina.co.za



AC-MI4006060