Make	HYUNDAI	
Model	i20 1.2 MOTION	
Vin	MALBM51BLLM75398	37
Engine Specifications	1.2	Petrol
Vehicle Type	H/B	
Service Plan	N/A	

Year	2020
Km	74191
Transmission	Manual
Colour	WHITE
Branch	Bosch Car Service
Warranty Plan	N/A

Interior					
Radio / Entertainment	Within Specification	-	Aircon Controls	Within Specification	•
Cluster	Within Specification	-	Electric Windows	Within Specification	•

Exterior					
Windscreen	Within Specification		Mag Wheels	Within Specification	-
Side Mirrors / Electric	Within Specification	lacksquare	Wiper Blades	Within Specification	•

BOSCH VEHICLE INSPECTION					
Engine					
Oil Service		74195 Km	Dip Stick	Within Specification	•
Oil Filter	Within Specification	_	Oil Filler Cap	Within Specification	•
Fuel/Diesel Filter	Within Specification	•	Fan Belt	Within Specification	•
Air Filter	Within Specification	~	Fan belt Tensioner	Within Specification	•
Cabin Filter	Within Specification	~	Alternator Belt	Within Specification	•
Spark Plugs	Within Specification	~	Power Steering Belt	Within Specification	•
Brake Fluid	Within Specification	—	Aircon Belt	Within Specification	•
Antifreeze	Within Specification	•	Multi V belt	Within Specification	~
Rear Main Seal	Within Specification	•	Engine Mountings	Within Specification	•
Sump/Gasket	Within Specification	•	PCV Valve	Within Specification	•

Braking System		
Front Brake Pads	-Select-	
Front Brake Discs	Within Specification	•
Front Brake Sensor	Not Applicable	•
Rear Brake Pads	-Select-	•
Rear Brake Discs	Within Specification	•
Rear Brake Sensor	Not Applicable	•
Rear Drums	Not Applicable	•
Rear Linings	-Select-	•
Brake Master	Within Specification	•
Hand Brake	Within Specification	•
Brake Calipers	Within Specification	•
Brake Hose	Within Specification	•

Cooling System		
Radiator	Within Specification	•
Radiator Hoses	Within Specification	•
Waterpump	Within Specification	-
Thermostat	Within Specification	•
Aircon Gas	Within Specification	•
Aircon Pump	Within Specification	•
Aircon Condensor	Within Specification	•
Interior Fan	Within Specification	•
Interior Radiator	Within Specification	•

Fueling System		
Intake Manifold	Within Specification	-
Throttle	Within Specification	•
Turbo	Within Specification	•
Injectors	Within Specification	-
Fuel Pump	Within Specification	•
Fuel Lines	Within Specification	lacksquare

Ignition System		
Ignition Coils	Within Specification	—
Glow Plugs	Not Applicable	•
Distrubutor	Not Applicable	—
HT Leads	Not Applicable	▼



BOSCH INSPECTION REPORT

Steering & Suspension		
Steering Rack	Within Specification	
Power Steering Pump	Within Specification	•
Wheel Alignment	Within Specification	
CV Joints	Within Specification	•
CV Boots	Within Specification	
Shocks Front	Within Specification	•
Shock Mountings Front	Within Specification	
Shocks Rear	Within Specification	
Stabilizer Links	Within Specification	•
Wheel Bearings	Within Specification	
Bearing Hubs	Within Specification	•
Control Arms	Within Specification	
Sideshafts/Seal	Within Specification	
Propshaft	Within Specification	
Wheel Nuts/Studs	Within Specification	—
Tyres & Spare	Within Specification	—
Mag Wheels/Hub Caps	Within Specification	•

Transmission & Clutch		
Clutch Kit	Within Specification	—
Clutch Master	Within Specification	~
Clutch Slave	Within Specification	•
Clutch Cable	Not Applicable	T
Gearbox	Within Specification	T
Gear & Diff oil	Within Specification	—
Auto Transmission	Not Applicable	—
Gear Selector	Within Specification	—
Gear Linkages	Within Specification	•

Ignition System		
Diagnostics	Within Specification	\
Cyl Leakage Test	Within Specification	\rightarrow
Road Test	Within Specification	~
Handling	Within Specification	~

Concluding Remarks	
Bosch Technician	General Comments
Ricardo Myburgh	
NEW Technician	Date of Inspection
	30-Jan-2025



