



Make	FORD	
Model	KUGA 1.5 ECOBOOST AMBIENTE A/T	
Vin	WF0AXXWPMABC76466	
Engine Specifications	1.5	Petrol
Vehicle Type	SUV	
Service Plan	N/A	

Year	2018
Km	129397
Transmission	Automatic
Colour	SILVER WHITE
Branch	Bosch Car Service
Warranty Plan	N/A

## Interior

The interior is in good condition , no visible damages

Radio / Entertainment	In good working order
Cluster	In good working order

Aircon Controls	In good working order
Electric Windows	In good working order

## Exterior

No visible damages, minor imperfections may be present

Windscreen	No visible damages
Side Mirrors / Electric	Within Specification

Mag Wheels	No visible damages
Wiper Blades	Acceptable for vehicle

## BOSCH VEHICLE INSPECTION

### Engine

Oil Service		119831 Km
Oil Filter	Within Specification	
Fuel/Diesel Filter	Within Specification	
Air Filter	Within Specification	
Cabin Filter	Within Specification	
Spark Plugs	Within Specification	
Brake Fluid	Very Good	Clean & free of contaminants
Antifreeze	Very Good	Level ok with required coolant ratio
Rear Main Seal	No Leaks	
Sump/Gasket	No Leaks	
Dip Stick	Very Good	



Oil Filler Cap	No Leaks	Sealed with no leaks
Fan Belt	Not Applicable	
Fan belt Tensioner	Not Applicable	No noise from tensioner
Alternator Belt	Not Applicable	
Power Steering Belt	Not Applicable	
Aircon Belt	Not Applicable	
Multi V belt	Within Specification	
Engine Mountings	Within Specification	
PCV Valve	Within Specification	Working as per manufacturers specification

---

Braking System		
Front Brake Pads	Very Good	90 %
Front Brake Discs	Within Specification	
Front Brake Sensor	Within Specification	
Rear Brake Pads	Very Good	60 %
Rear Brake Discs	Very Good	
Rear Brake Sensor	Within Specification	
Rear Drums	Not Applicable	
Rear Linings	Not Applicable	
Brake Master	Not Applicable	
Hand Brake	Within Specification	
Brake Calipers	Within Specification	
Brake Hose	Very Good	

Cooling System		
Radiator	No Leaks	
Radiator Hoses	No Leaks	
Waterpump	Renewed	
Thermostat	No Leaks	
Aircon Gas	Very Good	
Aircon Pump	No Leaks	
Aircon Condensor	Very Good	
Interior Fan	Very Good	
Interior Radiator	Within Specification	

---

Fueling System	
Intake Manifold	No Leaks
Throttle	Within Specification
Turbo	Not Applicable
Carburetor	Not Applicable
Injectors	No Fault Codes
Fuel Pump	Within Specification
Fuel Lines	No Leaks

Ignition System	
Ignition Coils	Within Specification
Glow Plugs	Not Applicable
Distributor	Not Applicable
HT Leads	Not Applicable

---



Steering & Suspension	
Steering Rack	Within Specification
Power Steering Pump	Not Applicable
Wheel Alignment	Within Specification
CV Joints	Very Good
CV Boots	Very Good
Shocks Front	No Leaks
Shock Mountings Front	Very Good
Shocks Rear	No Leaks
Stabilizer Links	Very Good
Wheel Bearings	Within Specification
Bearing Hubs	Within Specification
Control Arms	Within Specification
Sideshafts/Seal	Not Applicable
Propshaft	Not Applicable
Wheel Nuts/Studs	Very Good
Tyres & Spare	Within Specification
Mag Wheels/Hub Caps	Very Good

Transmission & Clutch	
Clutch Kit	Very Good
Clutch Master	Not Applicable
Clutch Slave	Not Applicable
Clutch Cable	Not Applicable
Gearbox	Very Good
Gear & Diff oil	Very Good
Auto Transmission	Within Specification
Gear Selector	Within Specification
Gear Linkages	Within Specification

Ignition System	
Diagnostics	Very Good
Cyl Leakage Test	Not Applicable
Test Drive	Very Good
Handling	Very Good

**Final Notes & Comments**

This vehicle inspection has been done impartially and to the best of our knowledge. This Bosch Inspection Report has been applied to all above items and are based the visual inspection and functionality thereof. Bosch cannot be held responsible for any unforeseen or concealed defects. The road test done within the confines of the inspection location. The vehicle is void of visual leaks or engine sludge build up and the vehicle is performing within acceptable and roadworthy conditions

**Bosch Technician**

Adriaan Rademeyer

**Date of Inspection**

2023-12-08



## BOSCH CAR SERVICE PRETORIA

a: 564 Steve Biko Road, Gezina, Pretoria 0084  
 t: 012 335 5737  
 e: reception@boschgezina.co.za



AC-MI4006060