

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name:Citton cars
Address:564 Steve Biko Road
Telephone:0123355737
Email:johan@boschgezina.co.za
Sn:988579800333
Time:2023-12-11 18:47:43
Technician Name:Adriaan
Customer Name:Citton cars

Vehicle Information

Year:2017
Make:FORD
Model:Kuga
VIN:WF0AXXWPMHHC76466
Displacement:G 1.6 MPI
Odometer:129402 km
Vehicle Software Version:V10.46

Inspection Result

The following systems are OK:

- 1.ABS (Anti-Lock Braking System)
- 2.ACM (Audio Control Module)
- 3.APIM (Accessory Protocol Interface Module)
- 4.BCMII (Body Control Module)
- 5.DDM (Driver Front Door Module)
- 6.FCIM (Front Controls Interface Module)
- 7.HVAC (Heating Ventilation Air Conditioning)
- 8.IPC (Instrument Panel Control Module)
- 9.PAM (Parking Aid Module)
- 10.PCM (Powertrain Control Module)
- 11.PDM (Passenger Front Door Module)
- 12.PSCM (Power Steering Control Module)
- 13.RCM (Restraint Control Module)
- 14.RFA (Remote Function Actuator)
- 15.SASM (Steering Angle Sensor Module)