



|                       |                                       |                                 |
|-----------------------|---------------------------------------|---------------------------------|
| Make                  | NISSAN                                |                                 |
| Model                 | NP200 1.5 DCi A/C SAFETY PACK P/U S/C |                                 |
| Vin                   | ADNUSN365U0167182                     |                                 |
| Engine Specifications | 1.5                                   | Diesel <input type="checkbox"/> |
| Vehicle Type          | S/C                                   |                                 |
| Service Plan          | N/A                                   |                                 |

|               |                                 |
|---------------|---------------------------------|
| Year          | 2018                            |
| Km            | 81046                           |
| Transmission  | Manual <input type="checkbox"/> |
| Colour        | WHITE                           |
| Branch        | Bosch Car Service               |
| Warranty Plan | N/A                             |

## Interior

The interior is in good condition , no visible damages

|                       |                                                |                  |                       |
|-----------------------|------------------------------------------------|------------------|-----------------------|
| Radio / Entertainment | In good working order <input type="checkbox"/> | Aircon Controls  | In good working order |
| Cluster               | -Select- <input type="checkbox"/>              | Electric Windows | In good working order |

## Exterior

No visible damages, minor imperfections may be present

|                         |                                                 |              |                                                 |
|-------------------------|-------------------------------------------------|--------------|-------------------------------------------------|
| Windscreen              | Acceptable for vehicle <input type="checkbox"/> | Mag Wheels   | Acceptable for vehicle <input type="checkbox"/> |
| Side Mirrors / Electric | Very Good <input type="checkbox"/>              | Wiper Blades | -Select- <input type="checkbox"/>               |

## BOSCH VEHICLE INSPECTION

### Engine

|                    |                                         |                                      |    |
|--------------------|-----------------------------------------|--------------------------------------|----|
| Oil Service        |                                         |                                      | Km |
| Oil Filter         | Very Good <input type="checkbox"/>      |                                      |    |
| Fuel/Diesel Filter | Very Good <input type="checkbox"/>      |                                      |    |
| Air Filter         | Very Good <input type="checkbox"/>      |                                      |    |
| Cabin Filter       | Very Good <input type="checkbox"/>      |                                      |    |
| Spark Plugs        | Not Applicable <input type="checkbox"/> |                                      |    |
| Brake Fluid        | Very Good <input type="checkbox"/>      | Clean & free of contaminants         |    |
| Antifreeze         | Very Good <input type="checkbox"/>      | Level ok with required coolant ratio |    |
| Rear Main Seal     | No Leaks <input type="checkbox"/>       |                                      |    |
| Sump/Gasket        | No Leaks <input type="checkbox"/>       |                                      |    |
| Dip Stick          | No Leaks <input type="checkbox"/>       |                                      |    |



|                     |                |                          |                                            |
|---------------------|----------------|--------------------------|--------------------------------------------|
| Oil Filler Cap      | No Leaks       | <input type="checkbox"/> | Sealed with no leaks                       |
| Fan Belt            | Very Good      | <input type="checkbox"/> |                                            |
| Fan belt Tensioner  | Very Good      | <input type="checkbox"/> | No noise from tensioner                    |
| Alternator Belt     | Very Good      | <input type="checkbox"/> |                                            |
| Power Steering Belt | Not Applicable | <input type="checkbox"/> |                                            |
| Aircon Belt         | Very Good      | <input type="checkbox"/> |                                            |
| Multi V belt        | Renewed        | <input type="checkbox"/> |                                            |
| Engine Mountings    | Very Good      | <input type="checkbox"/> |                                            |
| PCV Valve           | Very Good      | <input type="checkbox"/> | Working as per manufacturers specification |

| Braking System     |                      |                          |   |
|--------------------|----------------------|--------------------------|---|
| Front Brake Pads   | Renewed              | <input type="checkbox"/> | % |
| Front Brake Discs  | Within Specification | <input type="checkbox"/> |   |
| Front Brake Sensor | Not Applicable       | <input type="checkbox"/> |   |
| Rear Brake Pads    | Not Applicable       | <input type="checkbox"/> | % |
| Rear Brake Discs   | Not Applicable       | <input type="checkbox"/> |   |
| Rear Brake Sensor  | Not Applicable       | <input type="checkbox"/> |   |
| Rear Drums         | Within Specification | <input type="checkbox"/> |   |
| Rear Linings       | Within Specification | <input type="checkbox"/> |   |
| Brake Master       | No Leaks             | <input type="checkbox"/> |   |
| Hand Brake         | Very Good            | <input type="checkbox"/> |   |
| Brake Calipers     | Very Good            | <input type="checkbox"/> |   |
| Brake Hose         | No Leaks             | <input type="checkbox"/> |   |

| Cooling System    |                      |                          |  |
|-------------------|----------------------|--------------------------|--|
| Radiator          | No Leaks             | <input type="checkbox"/> |  |
| Radiator Hoses    | No Leaks             | <input type="checkbox"/> |  |
| Waterpump         | No Leaks             | <input type="checkbox"/> |  |
| Thermostat        | Within Specification | <input type="checkbox"/> |  |
| Aircon Gas        | No Leaks             | <input type="checkbox"/> |  |
| Aircon Pump       | Very Good            | <input type="checkbox"/> |  |
| Aircon Condensor  | No Leaks             | <input type="checkbox"/> |  |
| Interior Fan      | Very Good            | <input type="checkbox"/> |  |
| Interior Radiator | No Leaks             | <input type="checkbox"/> |  |

| Fueling System  |                      |                          |  |
|-----------------|----------------------|--------------------------|--|
| Intake Manifold | No Leaks             | <input type="checkbox"/> |  |
| Throttle        | Within Specification | <input type="checkbox"/> |  |
| Turbo           | Very Good            | <input type="checkbox"/> |  |
| Carburetor      | Not Applicable       | <input type="checkbox"/> |  |
| Injectors       | Within Specification | <input type="checkbox"/> |  |
| Fuel Pump       | Very Good            | <input type="checkbox"/> |  |
| Fuel Lines      | No Leaks             | <input type="checkbox"/> |  |

| Ignition System |                |                          |  |
|-----------------|----------------|--------------------------|--|
| Ignition Coils  | Not Applicable | <input type="checkbox"/> |  |
| Glow Plugs      | Very Good      | <input type="checkbox"/> |  |
| Distributor     | Not Applicable | <input type="checkbox"/> |  |
| HT Leads        | Not Applicable | <input type="checkbox"/> |  |



| Steering & Suspension |                      |   |
|-----------------------|----------------------|---|
| Steering Rack         | Very Good            | ▼ |
| Power Steering Pump   | Not Applicable       | ▼ |
| Wheel Alignment       | Within Specification | ▼ |
| CV Joints             | Very Good            | ▼ |
| CV Boots              | No Leaks             | ▼ |
| Shocks Front          | Renewed              | ▼ |
| Shock Mountings Front | Renewed              | ▼ |
| Shocks Rear           | Very Good            | ▼ |
| Stabilizer Links      | Very Good            | ▼ |
| Wheel Bearings        | Very Good            | ▼ |
| Bearing Hubs          | Within Specification | ▼ |
| Control Arms          | Very Good            | ▼ |
| Sideshafts/Seal       | No Leaks             | ▼ |
| Propshaft             | Not Applicable       | ▼ |
| Wheel Nuts/Studs      | Very Good            | ▼ |
| Tyres & Spare         | Very Good            | ▼ |
| Mag Wheels/Hub Caps   | Very Good            | ▼ |

| Transmission & Clutch |                      |   |
|-----------------------|----------------------|---|
| Clutch Kit            | Very Good            | ▼ |
| Clutch Master         | No Leaks             | ▼ |
| Clutch Slave          | No Leaks             | ▼ |
| Clutch Cable          | Not Applicable       | ▼ |
| Gearbox               | Very Good            | ▼ |
| Gear & Diff oil       | Within Specification | ▼ |
| Auto Transmission     | Not Applicable       | ▼ |
| Gear Selector         | Very Good            | ▼ |
| Gear Linkages         | Very Good            | ▼ |

| Ignition System  |                |   |
|------------------|----------------|---|
| Diagnostics      | No Fault Codes | ▼ |
| Cyl Leakage Test | No Leaks       | ▼ |
| Test Drive       | Very Good      | ▼ |
| Handling         | Very Good      | ▼ |

**Final Notes & Comments**

This vehicle inspection has been done impartially and to the best of our knowledge. This Bosch Inspection Report has been applied to all above items and are based the visual inspection and functionality thereof. Bosch cannot be held responsible for any unforeseen or concealed defects. The road test done within the confines of the inspection location. The vehicle is void of visual leaks or engine sludge build up and the vehicle is performing within acceptable and roadworthy conditions

**Bosch Technician**

-Select- ▼

**Date of Inspection**

2024-01-05



## BOSCH CAR SERVICE PRETORIA

a: 564 Steve Biko Road, Gezina, Pretoria 0084  
 t: 012 335 5737  
 e: reception@boschgezina.co.za



AC-MI4006060