

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name:Citton Cars
Address:564 Steve Biko Road
Telephone:0123355737
Email:johan@boschgezina.co.za
Sn:988579800333
Time:2024-01-05 15:56:45
Technician Name:Riaan
Customer Name:Given Rumo

Vehicle Information

Make:RENAULT
Model:LOGAN
VIN:ADNUSN365U0167182
Odometer:81046 km
Vehicle Software Version:V10.30

Inspection Result

The following systems are OK:
1.ECM (Engine Control Module)
2.ABS (Anti-lock Braking System)
3.UCH
4.SRS (Supplemental Inflatable Restraint System)
5.Variable P.A.S